

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
02 November 2024

| Time | Total | Cls 1 | Cls 2 | Cls 3 | Cls 4 | Cls 5 | Cls 6 | Cls 7 | Cls 8 | Cls 9 | Cls 10 | Cls 11 |
|------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|--------|--------|
| 0015 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0030 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0045 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0100 | 1 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0115 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0130 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0145 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0200 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0215 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0230 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0245 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0300 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0315 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0330 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0345 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0400 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0415 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0430 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0445 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0500 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0515 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0530 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0545 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0600 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0615 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0630 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0645 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0700 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0715 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0730 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0745 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0800 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0815 | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0830 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0845 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0900 | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0915 | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0930 | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0945 | 5 | 0 | 4 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 |
| 1000 | 3 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1015 | 1 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1030 | 4 | 0 | 3 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1045 | 4 | 1 | 1 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1100 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1115 | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1130 | 4 | 0 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1145 | 4 | 0 | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1200 | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1215 | 3 | 0 | 2 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1230 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1245 | 5 | 0 | 4 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
02 November 2024

| Time | Total | Cls 1 | Cls 2 | Cls 3 | Cls 4 | Cls 5 | Cls 6 | Cls 7 | Cls 8 | Cls 9 | Cls 10 | Cls 11 |
|--------------|------------|----------|------------|----------|----------|-----------|----------|----------|----------|----------|----------|----------|
| 1300 | 4 | 0 | 3 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1315 | 5 | 1 | 3 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1330 | 4 | 0 | 3 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1345 | 2 | 0 | 1 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1400 | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1415 | 3 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1430 | 3 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1445 | 4 | 0 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1500 | 7 | 1 | 4 | 0 | 1 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1515 | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1530 | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1545 | 3 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1600 | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1615 | 5 | 0 | 4 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1630 | 3 | 0 | 2 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1645 | 3 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1700 | 4 | 0 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1715 | 3 | 1 | 1 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1730 | 6 | 1 | 3 | 0 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1745 | 6 | 0 | 6 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1800 | 8 | 1 | 7 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1815 | 14 | 0 | 13 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1830 | 6 | 0 | 6 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1845 | 6 | 0 | 6 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1900 | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1915 | 5 | 0 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1930 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1945 | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2000 | 3 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2015 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2030 | 3 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2045 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2115 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2130 | 3 | 0 | 2 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2145 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2200 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2215 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2230 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2245 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2300 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2315 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2330 | 3 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2345 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2400 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 08-09 | 5 | 0 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 17-18 | 23 | 3 | 17 | 0 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 |
| 07-19 | 160 | 6 | 133 | 0 | 7 | 13 | 1 | 0 | 0 | 0 | 0 | 0 |
| 07-23 | 180 | 6 | 152 | 0 | 7 | 14 | 1 | 0 | 0 | 0 | 0 | 0 |
| 00-24 | 184 | 6 | 155 | 0 | 7 | 15 | 1 | 0 | 0 | 0 | 0 | 0 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
02 November 2024

| Time | Total | Cls 12 | CI% 1 | CI% 2 | CI% 3 | CI% 4 | CI% 5 | CI% 6 | CI% 7 | CI% 8 | CI% 9 | CI% 10 |
|------|-------|-----------|----------|----------|----------|----------|----------|----------|----------|----------|----------|-----------|
| 0015 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0030 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0045 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0100 | 1 | 0 | 0 | 0 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 |
| 0115 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0130 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0145 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0200 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0215 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0230 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0245 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0300 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0315 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0330 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0345 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0400 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0415 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0430 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0445 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0500 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0515 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0530 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0545 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0600 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0615 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0630 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0645 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0700 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0715 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0730 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0745 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0800 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0815 | 2 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0830 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0845 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0900 | 2 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0915 | 2 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0930 | 2 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0945 | 5 | 0 | 0 | 80 | 0 | 0 | 0 | 20 | 0 | 0 | 0 | 0 |
| 1000 | 3 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1015 | 1 | 0 | 0 | 0 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 |
| 1030 | 4 | 0 | 0 | 75 | 0 | 0 | 25 | 0 | 0 | 0 | 0 | 0 |
| 1045 | 4 | 0 | 25 | 25 | 0 | 50 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1100 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1115 | 2 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1130 | 4 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1145 | 4 | 0 | 0 | 50 | 0 | 50 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1200 | 2 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1215 | 3 | 0 | 0 | 66.67 | 0 | 33.33 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1230 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1245 | 5 | 0 | 0 | 80 | 0 | 0 | 20 | 0 | 0 | 0 | 0 | 0 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
02 November 2024

| Time | Total | Cls 12 | CI% 1 | CI% 2 | CI% 3 | CI% 4 | CI% 5 | CI% 6 | CI% 7 | CI% 8 | CI% 9 | CI% 10 |
|--------------|------------|-----------|--------------|--------------|----------|--------------|--------------|--------------|----------|----------|----------|-----------|
| 1300 | 4 | 0 | 0 | 75 | 0 | 0 | 25 | 0 | 0 | 0 | 0 | 0 |
| 1315 | 5 | 0 | 20 | 60 | 0 | 0 | 20 | 0 | 0 | 0 | 0 | 0 |
| 1330 | 4 | 0 | 0 | 75 | 0 | 25 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1345 | 2 | 0 | 0 | 50 | 0 | 0 | 50 | 0 | 0 | 0 | 0 | 0 |
| 1400 | 2 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1415 | 3 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1430 | 3 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1445 | 4 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1500 | 7 | 0 | 14.29 | 57.14 | 0 | 14.29 | 14.29 | 0 | 0 | 0 | 0 | 0 |
| 1515 | 2 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1530 | 2 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1545 | 3 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1600 | 2 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1615 | 5 | 0 | 0 | 80 | 0 | 0 | 20 | 0 | 0 | 0 | 0 | 0 |
| 1630 | 3 | 0 | 0 | 66.67 | 0 | 0 | 33.33 | 0 | 0 | 0 | 0 | 0 |
| 1645 | 3 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1700 | 4 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1715 | 3 | 0 | 33.33 | 33.33 | 0 | 0 | 33.33 | 0 | 0 | 0 | 0 | 0 |
| 1730 | 6 | 0 | 16.67 | 50 | 0 | 0 | 33.33 | 0 | 0 | 0 | 0 | 0 |
| 1745 | 6 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1800 | 8 | 0 | 12.5 | 87.5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1815 | 14 | 0 | 0 | 92.86 | 0 | 0 | 7.143 | 0 | 0 | 0 | 0 | 0 |
| 1830 | 6 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1845 | 6 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1900 | 2 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1915 | 5 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1930 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1945 | 2 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2000 | 3 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2015 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2030 | 3 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2045 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2100 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2115 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2130 | 3 | 0 | 0 | 66.67 | 0 | 0 | 33.33 | 0 | 0 | 0 | 0 | 0 |
| 2145 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2200 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2215 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2230 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2245 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2300 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2315 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2330 | 3 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2345 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2400 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 08-09 | 5 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 17-18 | 23 | 0 | 13.04 | 73.91 | 0 | 0 | 13.04 | 0 | 0 | 0 | 0 | 0 |
| 07-19 | 160 | 0 | 3.75 | 83.13 | 0 | 4.375 | 8.125 | 0.625 | 0 | 0 | 0 | 0 |
| 07-23 | 180 | 0 | 3.333 | 84.44 | 0 | 3.889 | 7.778 | 0.556 | 0 | 0 | 0 | 0 |
| 00-24 | 184 | 0 | 3.261 | 84.24 | 0 | 3.804 | 8.152 | 0.543 | 0 | 0 | 0 | 0 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
02 November 2024

| Time | Total | CI% 11 | CI% 12 | Vbin 0 5 | Vbin 5 10 | Vbin 10 15 | Vbin 15 20 | Vbin 20 25 | Vbin 25 30 | Vbin 30 35 | Vbin 35 40 | Vbin 40 45 |
|------|-------|-----------|-----------|----------------|-----------------|------------------|------------------|------------------|------------------|------------------|------------------|------------------|
| 0015 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0030 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0045 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0100 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 |
| 0115 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0130 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0145 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0200 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0215 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0230 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0245 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0300 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0315 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0330 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0345 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0400 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0415 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0430 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0445 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0500 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0515 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0530 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0545 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0600 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0615 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0630 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0645 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0700 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0715 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0730 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 |
| 0745 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 |
| 0800 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 |
| 0815 | 2 | 0 | 0 | 0 | 0 | 1 | 1 | 0 | 0 | 0 | 0 | 0 |
| 0830 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0845 | 1 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0900 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 2 | 0 | 0 | 0 | 0 |
| 0915 | 2 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 1 | 0 | 0 | 0 |
| 0930 | 2 | 0 | 0 | 0 | 0 | 0 | 2 | 0 | 0 | 0 | 0 | 0 |
| 0945 | 5 | 0 | 0 | 0 | 0 | 0 | 1 | 3 | 0 | 0 | 1 | 0 |
| 1000 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 2 | 0 | 0 |
| 1015 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 |
| 1030 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 2 | 2 | 0 | 0 | 0 |
| 1045 | 4 | 0 | 0 | 0 | 0 | 1 | 1 | 0 | 1 | 0 | 1 | 0 |
| 1100 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 |
| 1115 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 2 | 0 | 0 | 0 | 0 |
| 1130 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 4 | 0 | 0 | 0 | 0 |
| 1145 | 4 | 0 | 0 | 0 | 0 | 0 | 2 | 1 | 1 | 0 | 0 | 0 |
| 1200 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 1 | 0 |
| 1215 | 3 | 0 | 0 | 0 | 0 | 1 | 1 | 0 | 0 | 0 | 1 | 0 |
| 1230 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 |
| 1245 | 5 | 0 | 0 | 0 | 0 | 0 | 1 | 4 | 0 | 0 | 0 | 0 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
02 November 2024

| Time | Total | CI% 11 | CI% 12 | Vbin 0 5 | Vbin 5 10 | Vbin 10 15 | Vbin 15 20 | Vbin 20 25 | Vbin 25 30 | Vbin 30 35 | Vbin 35 40 | Vbin 40 45 |
|--------------|------------|-----------|-----------|----------------|-----------------|------------------|------------------|------------------|------------------|------------------|------------------|------------------|
| 1300 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 2 | 2 | 0 | 0 | 0 |
| 1315 | 5 | 0 | 0 | 0 | 0 | 1 | 0 | 4 | 0 | 0 | 0 | 0 |
| 1330 | 4 | 0 | 0 | 0 | 0 | 1 | 3 | 0 | 0 | 0 | 0 | 0 |
| 1345 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 2 | 0 | 0 | 0 | 0 |
| 1400 | 2 | 0 | 0 | 0 | 0 | 1 | 1 | 0 | 0 | 0 | 0 | 0 |
| 1415 | 3 | 0 | 0 | 0 | 0 | 1 | 1 | 1 | 0 | 0 | 0 | 0 |
| 1430 | 3 | 0 | 0 | 0 | 0 | 0 | 1 | 1 | 1 | 0 | 0 | 0 |
| 1445 | 4 | 0 | 0 | 0 | 0 | 0 | 1 | 3 | 0 | 0 | 0 | 0 |
| 1500 | 7 | 0 | 0 | 0 | 0 | 0 | 1 | 6 | 0 | 0 | 0 | 0 |
| 1515 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 2 | 0 | 0 | 0 |
| 1530 | 2 | 0 | 0 | 0 | 0 | 0 | 1 | 1 | 0 | 0 | 0 | 0 |
| 1545 | 3 | 0 | 0 | 0 | 0 | 0 | 2 | 1 | 0 | 0 | 0 | 0 |
| 1600 | 2 | 0 | 0 | 0 | 0 | 0 | 1 | 1 | 0 | 0 | 0 | 0 |
| 1615 | 5 | 0 | 0 | 0 | 0 | 0 | 1 | 4 | 0 | 0 | 0 | 0 |
| 1630 | 3 | 0 | 0 | 0 | 0 | 1 | 2 | 0 | 0 | 0 | 0 | 0 |
| 1645 | 3 | 0 | 0 | 0 | 0 | 0 | 2 | 0 | 1 | 0 | 0 | 0 |
| 1700 | 4 | 0 | 0 | 0 | 0 | 0 | 1 | 2 | 0 | 1 | 0 | 0 |
| 1715 | 3 | 0 | 0 | 0 | 0 | 0 | 2 | 0 | 1 | 0 | 0 | 0 |
| 1730 | 6 | 0 | 0 | 0 | 0 | 0 | 4 | 2 | 0 | 0 | 0 | 0 |
| 1745 | 6 | 0 | 0 | 0 | 0 | 2 | 4 | 0 | 0 | 0 | 0 | 0 |
| 1800 | 8 | 0 | 0 | 0 | 0 | 2 | 4 | 1 | 1 | 0 | 0 | 0 |
| 1815 | 14 | 0 | 0 | 1 | 0 | 4 | 6 | 2 | 1 | 0 | 0 | 0 |
| 1830 | 6 | 0 | 0 | 0 | 1 | 0 | 4 | 0 | 1 | 0 | 0 | 0 |
| 1845 | 6 | 0 | 0 | 0 | 0 | 2 | 4 | 0 | 0 | 0 | 0 | 0 |
| 1900 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 2 | 0 | 0 | 0 | 0 |
| 1915 | 5 | 0 | 0 | 0 | 0 | 2 | 3 | 0 | 0 | 0 | 0 | 0 |
| 1930 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 |
| 1945 | 2 | 0 | 0 | 0 | 0 | 0 | 1 | 1 | 0 | 0 | 0 | 0 |
| 2000 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 2 | 1 | 0 | 0 |
| 2015 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2030 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 2 | 0 | 0 | 0 |
| 2045 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2100 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2115 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2130 | 3 | 0 | 0 | 1 | 0 | 0 | 2 | 0 | 0 | 0 | 0 | 0 |
| 2145 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2200 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2215 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 |
| 2230 | 1 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 |
| 2245 | 1 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 |
| 2300 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2315 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2330 | 3 | 0 | 0 | 0 | 0 | 1 | 0 | 2 | 0 | 0 | 0 | 0 |
| 2345 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2400 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 08-09 | 5 | 0 | 0 | 0 | 0 | 2 | 1 | 2 | 0 | 0 | 0 | 0 |
| 17-18 | 23 | 0 | 0 | 0 | 0 | 4 | 14 | 3 | 2 | 0 | 0 | 0 |
| 07-19 | 160 | 0 | 0 | 1 | 2 | 19 | 55 | 58 | 18 | 3 | 4 | 0 |
| 07-23 | 180 | 0 | 0 | 2 | 2 | 21 | 63 | 61 | 23 | 4 | 4 | 0 |
| 00-24 | 184 | 0 | 0 | 2 | 2 | 22 | 63 | 64 | 23 | 4 | 4 | 0 |

Site Name - 24379-09
 Description - Cleveland Walk, East of Bathwick Hill
 Direction - West
 02 November 2024

| Time | Total | Vpp 85 | Mean | SD |
|------|-------|-----------|--------|------|
| 0015 | 0 - | - | - | - |
| 0030 | 0 - | - | - | - |
| 0045 | 0 - | - | - | - |
| 0100 | 1 - | - | 24.9 - | - |
| 0115 | 0 - | - | - | - |
| 0130 | 0 - | - | - | - |
| 0145 | 0 - | - | - | - |
| 0200 | 0 - | - | - | - |
| 0215 | 0 - | - | - | - |
| 0230 | 0 - | - | - | - |
| 0245 | 0 - | - | - | - |
| 0300 | 0 - | - | - | - |
| 0315 | 0 - | - | - | - |
| 0330 | 0 - | - | - | - |
| 0345 | 0 - | - | - | - |
| 0400 | 0 - | - | - | - |
| 0415 | 0 - | - | - | - |
| 0430 | 0 - | - | - | - |
| 0445 | 0 - | - | - | - |
| 0500 | 0 - | - | - | - |
| 0515 | 0 - | - | - | - |
| 0530 | 0 - | - | - | - |
| 0545 | 0 - | - | - | - |
| 0600 | 0 - | - | - | - |
| 0615 | 0 - | - | - | - |
| 0630 | 0 - | - | - | - |
| 0645 | 0 - | - | - | - |
| 0700 | 0 - | - | - | - |
| 0715 | 0 - | - | - | - |
| 0730 | 1 - | - | 28 - | - |
| 0745 | 1 - | - | 25.7 - | - |
| 0800 | 1 - | - | 25.7 - | - |
| 0815 | 2 - | - | 15.8 | 3.3 |
| 0830 | 0 - | - | - | - |
| 0845 | 1 - | - | 12.9 - | - |
| 0900 | 2 - | - | 21 | 0 |
| 0915 | 2 - | - | 16.6 | 14.3 |
| 0930 | 2 - | - | 19.5 | 0.3 |
| 0945 | 5 - | - | 24 | 7.5 |
| 1000 | 3 - | - | 27.7 | 6.2 |
| 1015 | 1 - | - | 22.4 - | - |
| 1030 | 4 - | - | 23.9 | 1.8 |
| 1045 | 4 - | - | 23.7 | 12 |
| 1100 | 1 - | - | 23.6 - | - |
| 1115 | 2 - | - | 23.5 | 0.7 |
| 1130 | 4 - | - | 22 | 1.6 |
| 1145 | 4 - | - | 21.1 | 6.2 |
| 1200 | 2 - | - | 30.6 | 10 |
| 1215 | 3 - | - | 21.4 | 14 |
| 1230 | 1 - | - | 22.5 - | - |
| 1245 | 5 - | - | 22.7 | 1.6 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
02 November 2024

| Time | Total | Vpp 85 | Mean | SD |
|--------------|------------|-------------|-------------|------------|
| 1300 | 4 - | | 24 | 3.4 |
| 1315 | 5 - | | 21.3 | 4.7 |
| 1330 | 4 - | | 16.1 | 1.7 |
| 1345 | 2 - | | 22.1 | 2.3 |
| 1400 | 2 - | | 14.5 | 4.6 |
| 1415 | 3 - | | 18.7 | 4.6 |
| 1430 | 3 - | | 22.5 | 6 |
| 1445 | 4 - | | 20.9 | 3.7 |
| 1500 | 7 - | | 22.4 | 2.3 |
| 1515 | 2 - | | 28.2 | 0.8 |
| 1530 | 2 - | | 20.3 | 4.2 |
| 1545 | 3 - | | 17.5 | 3.2 |
| 1600 | 2 - | | 20.9 | 3.4 |
| 1615 | 5 - | | 21.3 | 1.5 |
| 1630 | 3 - | | 17.5 | 3.3 |
| 1645 | 3 - | | 22.8 | 5 |
| 1700 | 4 - | | 24.7 | 5.5 |
| 1715 | 3 - | | 19.9 | 5 |
| 1730 | 6 - | | 20.1 | 3 |
| 1745 | 6 - | | 15.7 | 2.1 |
| 1800 | 8 - | | 17 | 4.2 |
| 1815 | 14 | 23.9 | 16.6 | 6.2 |
| 1830 | 6 - | | 18.4 | 6.1 |
| 1845 | 6 - | | 16.6 | 3.1 |
| 1900 | 2 - | | 22.8 | 0.2 |
| 1915 | 5 - | | 15.5 | 3 |
| 1930 | 1 - | | 29.5 - | |
| 1945 | 2 - | | 20.5 | 4 |
| 2000 | 3 - | | 29.2 | 3.7 |
| 2015 | 0 - | | - | |
| 2030 | 3 - | | 24.6 | 1.1 |
| 2045 | 0 - | | - | |
| 2100 | 0 - | | - | |
| 2115 | 0 - | | - | |
| 2130 | 3 - | | 14.3 | 8.3 |
| 2145 | 0 - | | - | |
| 2200 | 0 - | | - | |
| 2215 | 1 - | | 21.9 - | |
| 2230 | 1 - | | 16.3 - | |
| 2245 | 1 - | | 18.7 - | |
| 2300 | 0 - | | - | |
| 2315 | 0 - | | - | |
| 2330 | 3 - | | 20.1 | 5.4 |
| 2345 | 0 - | | - | |
| 2400 | 0 - | | - | |
| 08-09 | 5 - | | 17.3 | 3.9 |
| 17-18 | 23 | 23.3 | 17.8 | 3.8 |
| 07-19 | 160 | 25.2 | 20.5 | 5.6 |
| 07-23 | 180 | 25.3 | 20.5 | 5.7 |
| 00-24 | 184 | 25.3 | 20.5 | 5.7 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
03 November 2024

| Time | Total | Cls 1 | Cls 2 | Cls 3 | Cls 4 | Cls 5 | Cls 6 | Cls 7 | Cls 8 | Cls 9 | Cls 10 | Cls 11 |
|--------------|------------|----------|------------|----------|----------|-----------|----------|----------|----------|----------|----------|----------|
| 1300 | 8 | 0 | 7 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1315 | 4 | 0 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1330 | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1345 | 5 | 0 | 4 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 |
| 1400 | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1415 | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1430 | 3 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1445 | 3 | 0 | 2 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1500 | 6 | 0 | 6 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1515 | 3 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1530 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1545 | 6 | 1 | 4 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1600 | 4 | 0 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1615 | 4 | 0 | 2 | 0 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1630 | 9 | 0 | 7 | 0 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1645 | 4 | 0 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1700 | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1715 | 2 | 0 | 1 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1730 | 3 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1745 | 3 | 1 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1800 | 2 | 0 | 1 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1815 | 1 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1830 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1845 | 3 | 0 | 1 | 0 | 1 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1900 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1915 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1930 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1945 | 1 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2000 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2015 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2030 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2045 | 2 | 0 | 1 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2115 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2130 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2145 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2200 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2215 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2230 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2245 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2300 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2315 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2330 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2345 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2400 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 08-09 | 3 | 0 | 2 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 17-18 | 10 | 1 | 7 | 0 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 |
| 07-19 | 128 | 5 | 105 | 0 | 1 | 16 | 1 | 0 | 0 | 0 | 0 | 0 |
| 07-23 | 133 | 6 | 108 | 0 | 1 | 17 | 1 | 0 | 0 | 0 | 0 | 0 |
| 00-24 | 137 | 6 | 112 | 0 | 1 | 17 | 1 | 0 | 0 | 0 | 0 | 0 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
03 November 2024

| Time | Total | Cls 12 | CI% 1 | CI% 2 | CI% 3 | CI% 4 | CI% 5 | CI% 6 | CI% 7 | CI% 8 | CI% 9 | CI% 10 |
|--------------|------------|-----------|--------------|--------------|----------|--------------|--------------|--------------|----------|----------|----------|-----------|
| 1300 | 8 | 0 | 0 | 87.5 | 0 | 0 | 12.5 | 0 | 0 | 0 | 0 | 0 |
| 1315 | 4 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1330 | 2 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1345 | 5 | 0 | 0 | 80 | 0 | 0 | 0 | 20 | 0 | 0 | 0 | 0 |
| 1400 | 2 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1415 | 2 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1430 | 3 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1445 | 3 | 0 | 0 | 66.67 | 0 | 0 | 33.33 | 0 | 0 | 0 | 0 | 0 |
| 1500 | 6 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1515 | 3 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1530 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1545 | 6 | 0 | 16.67 | 66.67 | 0 | 0 | 16.67 | 0 | 0 | 0 | 0 | 0 |
| 1600 | 4 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1615 | 4 | 0 | 0 | 50 | 0 | 0 | 50 | 0 | 0 | 0 | 0 | 0 |
| 1630 | 9 | 0 | 0 | 77.78 | 0 | 0 | 22.22 | 0 | 0 | 0 | 0 | 0 |
| 1645 | 4 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1700 | 2 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1715 | 2 | 0 | 0 | 50 | 0 | 0 | 50 | 0 | 0 | 0 | 0 | 0 |
| 1730 | 3 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1745 | 3 | 0 | 33.33 | 66.67 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1800 | 2 | 0 | 0 | 50 | 0 | 0 | 50 | 0 | 0 | 0 | 0 | 0 |
| 1815 | 1 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1830 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 1845 | 3 | 0 | 0 | 33.33 | 0 | 33.33 | 33.33 | 0 | 0 | 0 | 0 | 0 |
| 1900 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 1915 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 1930 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 1945 | 1 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2000 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2015 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2030 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2045 | 2 | 0 | 0 | 50 | 0 | 0 | 50 | 0 | 0 | 0 | 0 | 0 |
| 2100 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2115 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2130 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2145 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2200 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2215 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2230 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2245 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2300 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2315 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2330 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2345 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2400 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 08-09 | 3 | 0 | 0 | 66.67 | 0 | 0 | 33.33 | 0 | 0 | 0 | 0 | 0 |
| 17-18 | 10 | 0 | 10 | 70 | 0 | 0 | 20 | 0 | 0 | 0 | 0 | 0 |
| 07-19 | 128 | 0 | 3.906 | 82.03 | 0 | 0.781 | 12.5 | 0.781 | 0 | 0 | 0 | 0 |
| 07-23 | 133 | 0 | 4.511 | 81.2 | 0 | 0.752 | 12.78 | 0.752 | 0 | 0 | 0 | 0 |
| 00-24 | 137 | 0 | 4.38 | 81.75 | 0 | 0.73 | 12.41 | 0.73 | 0 | 0 | 0 | 0 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
03 November 2024

| Time | Total | CI% 11 | CI% 12 | Vbin 0 5 | Vbin 5 10 | Vbin 10 15 | Vbin 15 20 | Vbin 20 25 | Vbin 25 30 | Vbin 30 35 | Vbin 35 40 | Vbin 40 45 |
|------|-------|-----------|-----------|----------------|-----------------|------------------|------------------|------------------|------------------|------------------|------------------|------------------|
| 0015 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 |
| 0030 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 2 | 0 | 0 | 0 | 0 |
| 0045 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0100 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 |
| 0115 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0130 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0145 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0200 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0215 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0230 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0245 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0300 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0315 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0330 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0345 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0400 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0415 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0430 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0445 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0500 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0515 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0530 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0545 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0600 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0615 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0630 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0645 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0700 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0715 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 |
| 0730 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0745 | 1 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 |
| 0800 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0815 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 |
| 0830 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 |
| 0845 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0900 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 |
| 0915 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0930 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 3 | 0 | 0 | 0 |
| 0945 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1000 | 3 | 0 | 0 | 0 | 0 | 0 | 2 | 1 | 0 | 0 | 0 | 0 |
| 1015 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1030 | 4 | 0 | 0 | 0 | 0 | 1 | 1 | 1 | 1 | 0 | 0 | 0 |
| 1045 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 |
| 1100 | 3 | 0 | 0 | 0 | 0 | 1 | 1 | 1 | 0 | 0 | 0 | 0 |
| 1115 | 7 | 0 | 0 | 0 | 0 | 0 | 1 | 1 | 5 | 0 | 0 | 0 |
| 1130 | 4 | 0 | 0 | 0 | 0 | 0 | 2 | 1 | 1 | 0 | 0 | 0 |
| 1145 | 4 | 0 | 0 | 0 | 0 | 0 | 1 | 1 | 2 | 0 | 0 | 0 |
| 1200 | 2 | 0 | 0 | 0 | 0 | 0 | 1 | 1 | 0 | 0 | 0 | 0 |
| 1215 | 8 | 0 | 0 | 0 | 1 | 0 | 2 | 3 | 2 | 0 | 0 | 0 |
| 1230 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1245 | 1 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
03 November 2024

| Time | Total | CI% 11 | CI% 12 | Vbin 0 5 | Vbin 5 10 | Vbin 10 15 | Vbin 15 20 | Vbin 20 25 | Vbin 25 30 | Vbin 30 35 | Vbin 35 40 | Vbin 40 45 |
|--------------|------------|-----------|-----------|----------------|-----------------|------------------|------------------|------------------|------------------|------------------|------------------|------------------|
| 1300 | 8 | 0 | 0 | 0 | 0 | 0 | 2 | 5 | 1 | 0 | 0 | 0 |
| 1315 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 3 | 0 | 0 | 0 |
| 1330 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 1 | 0 | 0 | 0 |
| 1345 | 5 | 0 | 0 | 0 | 0 | 0 | 1 | 3 | 1 | 0 | 0 | 0 |
| 1400 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 2 | 0 | 0 | 0 | 0 |
| 1415 | 2 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 1 | 0 | 0 | 0 |
| 1430 | 3 | 0 | 0 | 0 | 1 | 0 | 0 | 2 | 0 | 0 | 0 | 0 |
| 1445 | 3 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 2 | 0 | 0 | 0 |
| 1500 | 6 | 0 | 0 | 0 | 0 | 1 | 1 | 3 | 1 | 0 | 0 | 0 |
| 1515 | 3 | 0 | 0 | 0 | 0 | 0 | 2 | 1 | 0 | 0 | 0 | 0 |
| 1530 | 1 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 |
| 1545 | 6 | 0 | 0 | 0 | 0 | 0 | 1 | 4 | 1 | 0 | 0 | 0 |
| 1600 | 4 | 0 | 0 | 0 | 0 | 1 | 1 | 2 | 0 | 0 | 0 | 0 |
| 1615 | 4 | 0 | 0 | 0 | 0 | 0 | 2 | 0 | 2 | 0 | 0 | 0 |
| 1630 | 9 | 0 | 0 | 0 | 0 | 0 | 1 | 6 | 1 | 1 | 0 | 0 |
| 1645 | 4 | 0 | 0 | 0 | 0 | 0 | 1 | 3 | 0 | 0 | 0 | 0 |
| 1700 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 1 | 0 | 0 | 0 |
| 1715 | 2 | 0 | 0 | 0 | 0 | 0 | 1 | 1 | 0 | 0 | 0 | 0 |
| 1730 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 3 | 0 | 0 | 0 | 0 |
| 1745 | 3 | 0 | 0 | 0 | 1 | 0 | 0 | 1 | 0 | 1 | 0 | 0 |
| 1800 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 2 | 0 | 0 | 0 | 0 |
| 1815 | 1 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1830 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1845 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 3 | 0 | 0 | 0 | 0 |
| 1900 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1915 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1930 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1945 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 |
| 2000 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2015 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 |
| 2030 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2045 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 2 | 0 | 0 | 0 | 0 |
| 2100 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2115 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2130 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2145 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2200 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2215 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2230 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2245 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2300 | 1 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 |
| 2315 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2330 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2345 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2400 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 08-09 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 2 | 1 | 0 | 0 | 0 |
| 17-18 | 10 | 0 | 0 | 0 | 1 | 0 | 1 | 7 | 0 | 1 | 0 | 0 |
| 07-19 | 128 | 0 | 0 | 0 | 3 | 5 | 29 | 59 | 30 | 2 | 0 | 0 |
| 07-23 | 133 | 0 | 0 | 0 | 3 | 5 | 30 | 63 | 30 | 2 | 0 | 0 |
| 00-24 | 137 | 0 | 0 | 0 | 3 | 5 | 30 | 65 | 32 | 2 | 0 | 0 |

Site Name - 24379-09
 Description - Cleveland Walk, East of Bathwick Hill
 Direction - West
 03 November 2024

| Time | Total | Vpp 85 | Mean | SD |
|------|-------|-----------|--------|-----|
| 0015 | 1 - | | 26.3 - | |
| 0030 | 2 - | | 22.1 | 0 |
| 0045 | 0 - | - | - | |
| 0100 | 1 - | | 26.4 - | |
| 0115 | 0 - | - | - | |
| 0130 | 0 - | - | - | |
| 0145 | 0 - | - | - | |
| 0200 | 0 - | - | - | |
| 0215 | 0 - | - | - | |
| 0230 | 0 - | - | - | |
| 0245 | 0 - | - | - | |
| 0300 | 0 - | - | - | |
| 0315 | 0 - | - | - | |
| 0330 | 0 - | - | - | |
| 0345 | 0 - | - | - | |
| 0400 | 0 - | - | - | |
| 0415 | 0 - | - | - | |
| 0430 | 0 - | - | - | |
| 0445 | 0 - | - | - | |
| 0500 | 0 - | - | - | |
| 0515 | 0 - | - | - | |
| 0530 | 0 - | - | - | |
| 0545 | 0 - | - | - | |
| 0600 | 0 - | - | - | |
| 0615 | 0 - | - | - | |
| 0630 | 0 - | - | - | |
| 0645 | 0 - | - | - | |
| 0700 | 0 - | - | - | |
| 0715 | 1 - | | 23.6 - | |
| 0730 | 0 - | - | - | |
| 0745 | 1 - | | 17.1 - | |
| 0800 | 0 - | - | - | |
| 0815 | 1 - | | 25.1 - | |
| 0830 | 1 - | | 23.1 - | |
| 0845 | 0 - | - | - | |
| 0900 | 1 - | | 22.2 - | |
| 0915 | 0 - | - | - | |
| 0930 | 4 - | | 25.1 | 1.7 |
| 0945 | 0 - | - | - | |
| 1000 | 3 - | | 19.5 | 4.1 |
| 1015 | 0 - | - | - | |
| 1030 | 4 - | | 19.6 | 5.3 |
| 1045 | 1 - | | 21.9 - | |
| 1100 | 3 - | | 16.9 | 4.1 |
| 1115 | 7 - | | 24.7 | 2.7 |
| 1130 | 4 - | | 20 | 3.9 |
| 1145 | 4 - | | 24.5 | 4.8 |
| 1200 | 2 - | | 19.5 | 2.2 |
| 1215 | 8 - | | 20.2 | 7.2 |
| 1230 | 0 - | - | - | |
| 1245 | 1 - | | 18.8 - | |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
03 November 2024

| Time | Total | Vpp 85 | Mean | SD |
|--------------|-------------|-------------|-------------|------------|
| 1300 | 8 - | | 22 | 3.6 |
| 1315 | 4 - | | 25.5 | 3 |
| 1330 | 2 - | | 25.1 | 0.8 |
| 1345 | 5 - | | 21.6 | 3.5 |
| 1400 | 2 - | | 23.7 | 0.1 |
| 1415 | 2 - | | 22.7 | 6.2 |
| 1430 | 3 - | | 17.9 | 7.6 |
| 1445 | 3 - | | 24.2 | 4.7 |
| 1500 | 6 - | | 21.5 | 5 |
| 1515 | 3 - | | 18.3 | 1.7 |
| 1530 | 1 - | | 17.4 - | |
| 1545 | 6 - | | 23.1 | 3.3 |
| 1600 | 4 - | | 18.8 | 4.1 |
| 1615 | 4 - | | 22.5 | 4.2 |
| 1630 | 9 - | | 23.9 | 3.9 |
| 1645 | 4 - | | 20.2 | 1.7 |
| 1700 | 2 - | | 25.1 | 1.7 |
| 1715 | 2 - | | 20.8 | 1.3 |
| 1730 | 3 - | | 21.6 | 1.2 |
| 1745 | 3 - | | 21.3 | 10.9 |
| 1800 | 2 - | | 23.7 | 0.7 |
| 1815 | 1 - | | 14.2 - | |
| 1830 | 0 - | - | - | |
| 1845 | 3 - | | 23.1 | 1.2 |
| 1900 | 0 - | - | - | |
| 1915 | 0 - | - | - | |
| 1930 | 0 - | - | - | |
| 1945 | 1 - | | 22.9 - | |
| 2000 | 0 - | - | - | |
| 2015 | 1 - | | 23.6 - | |
| 2030 | 0 - | - | - | |
| 2045 | 2 - | | 22.6 | 2.4 |
| 2100 | 0 - | - | - | |
| 2115 | 0 - | - | - | |
| 2130 | 0 - | - | - | |
| 2145 | 0 - | - | - | |
| 2200 | 0 - | - | - | |
| 2215 | 0 - | - | - | |
| 2230 | 0 - | - | - | |
| 2245 | 0 - | - | - | |
| 2300 | 1 - | | 15.6 - | |
| 2315 | 0 - | - | - | |
| 2330 | 0 - | - | - | |
| 2345 | 0 - | - | - | |
| 2400 | 0 - | - | - | |
| 08-09 | 3 - | | 23.5 | 1.4 |
| 17-18 | 10 - | | 21.8 | 5.3 |
| 07-19 | 128 | 26.2 | 21.9 | 4.4 |
| 07-23 | 133 | 26.1 | 21.8 | 4.3 |
| 00-24 | 137 | 26.2 | 21.9 | 4.3 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
04 November 2024

| Time | Total | Cls 1 | Cls 2 | Cls 3 | Cls 4 | Cls 5 | Cls 6 | Cls 7 | Cls 8 | Cls 9 | Cls 10 | Cls 11 |
|------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|--------|--------|
| 0015 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0030 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0045 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0115 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0130 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0145 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0200 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0215 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0230 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0245 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0300 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0315 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0330 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0345 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0400 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0415 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0430 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0445 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0500 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0515 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0530 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0545 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0600 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0615 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0630 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0645 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0700 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0715 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0730 | 3 | 0 | 0 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0745 | 4 | 0 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0800 | 6 | 0 | 5 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0815 | 15 | 0 | 13 | 0 | 1 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0830 | 35 | 0 | 32 | 0 | 0 | 2 | 1 | 0 | 0 | 0 | 0 | 0 |
| 0845 | 27 | 0 | 25 | 0 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0900 | 7 | 1 | 6 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0915 | 8 | 0 | 7 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0930 | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0945 | 1 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1000 | 4 | 0 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1015 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1030 | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1045 | 8 | 1 | 5 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1100 | 3 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1115 | 6 | 0 | 5 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1130 | 5 | 0 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1145 | 3 | 0 | 1 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1200 | 5 | 1 | 3 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1215 | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1230 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1245 | 4 | 0 | 3 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
04 November 2024

| Time | Total | Cls 1 | Cls 2 | Cls 3 | Cls 4 | Cls 5 | Cls 6 | Cls 7 | Cls 8 | Cls 9 | Cls 10 | Cls 11 |
|--------------|------------|----------|------------|----------|-----------|-----------|----------|----------|----------|----------|----------|----------|
| 1300 | 6 | 0 | 6 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1315 | 4 | 0 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1330 | 6 | 0 | 6 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1345 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1400 | 9 | 0 | 7 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1415 | 4 | 0 | 2 | 0 | 1 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1430 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1445 | 4 | 0 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1500 | 5 | 0 | 4 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1515 | 4 | 0 | 3 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1530 | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1545 | 11 | 1 | 10 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1600 | 8 | 0 | 6 | 0 | 1 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1615 | 39 | 0 | 32 | 0 | 0 | 7 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1630 | 12 | 0 | 9 | 0 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1645 | 11 | 1 | 8 | 0 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1700 | 6 | 0 | 4 | 0 | 1 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1715 | 8 | 0 | 5 | 0 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1730 | 10 | 1 | 9 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1745 | 12 | 0 | 11 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1800 | 13 | 1 | 11 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1815 | 3 | 0 | 2 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1830 | 4 | 0 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1845 | 4 | 0 | 3 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1900 | 3 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1915 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1930 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1945 | 2 | 0 | 1 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2000 | 3 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2015 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2030 | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2045 | 3 | 0 | 2 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2100 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2115 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2130 | 2 | 0 | 1 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2145 | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2200 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2215 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2230 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2245 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2300 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2315 | 3 | 0 | 2 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2330 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2345 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2400 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 08-09 | 84 | 1 | 76 | 0 | 1 | 5 | 1 | 0 | 0 | 0 | 0 | 0 |
| 17-18 | 43 | 2 | 36 | 0 | 0 | 5 | 0 | 0 | 0 | 0 | 0 | 0 |
| 07-19 | 341 | 7 | 285 | 0 | 17 | 31 | 1 | 0 | 0 | 0 | 0 | 0 |
| 07-23 | 359 | 7 | 300 | 0 | 17 | 34 | 1 | 0 | 0 | 0 | 0 | 0 |
| 00-24 | 363 | 7 | 303 | 0 | 17 | 35 | 1 | 0 | 0 | 0 | 0 | 0 |

Site Name - 24379-09
 Description - Cleveland Walk, East of Bathwick Hill
 Direction - West
 04 November 2024

| Time | Total | Cls 12 | CI% 1 | CI% 2 | CI% 3 | CI% 4 | CI% 5 | CI% 6 | CI% 7 | CI% 8 | CI% 9 | CI% 10 |
|------|-------|-----------|----------|----------|----------|----------|----------|----------|----------|----------|----------|-----------|
| 0015 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0030 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0045 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0100 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0115 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0130 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0145 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0200 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0215 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0230 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0245 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0300 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0315 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0330 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0345 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0400 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0415 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0430 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0445 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0500 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0515 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0530 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0545 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0600 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0615 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0630 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0645 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0700 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0715 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0730 | 3 | 0 | 0 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0745 | 4 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0800 | 6 | 0 | 0 | 83.33 | 0 | 0 | 16.67 | 0 | 0 | 0 | 0 | 0 |
| 0815 | 15 | 0 | 0 | 86.67 | 0 | 6.667 | 6.667 | 0 | 0 | 0 | 0 | 0 |
| 0830 | 35 | 0 | 0 | 91.43 | 0 | 0 | 5.714 | 2.857 | 0 | 0 | 0 | 0 |
| 0845 | 27 | 0 | 0 | 92.59 | 0 | 0 | 7.407 | 0 | 0 | 0 | 0 | 0 |
| 0900 | 7 | 0 | 14.29 | 85.71 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0915 | 8 | 0 | 0 | 87.5 | 0 | 0 | 12.5 | 0 | 0 | 0 | 0 | 0 |
| 0930 | 2 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0945 | 1 | 0 | 0 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1000 | 4 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1015 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 1030 | 2 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1045 | 8 | 0 | 12.5 | 62.5 | 0 | 25 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1100 | 3 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1115 | 6 | 0 | 0 | 83.33 | 0 | 0 | 16.67 | 0 | 0 | 0 | 0 | 0 |
| 1130 | 5 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1145 | 3 | 0 | 0 | 33.33 | 0 | 66.67 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1200 | 5 | 0 | 20 | 60 | 0 | 20 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1215 | 2 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1230 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1245 | 4 | 0 | 0 | 75 | 0 | 25 | 0 | 0 | 0 | 0 | 0 | 0 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
04 November 2024

| Time | Total | Cls 12 | CI% 1 | CI% 2 | CI% 3 | CI% 4 | CI% 5 | CI% 6 | CI% 7 | CI% 8 | CI% 9 | CI% 10 |
|--------------|------------|----------|--------------|--------------|----------|--------------|--------------|--------------|----------|----------|----------|----------|
| 1300 | 6 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1315 | 4 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1330 | 6 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1345 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1400 | 9 | 0 | 0 | 77.78 | 0 | 22.22 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1415 | 4 | 0 | 0 | 50 | 0 | 25 | 25 | 0 | 0 | 0 | 0 | 0 |
| 1430 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1445 | 4 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1500 | 5 | 0 | 0 | 80 | 0 | 20 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1515 | 4 | 0 | 0 | 75 | 0 | 0 | 25 | 0 | 0 | 0 | 0 | 0 |
| 1530 | 2 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1545 | 11 | 0 | 9.091 | 90.91 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1600 | 8 | 0 | 0 | 75 | 0 | 12.5 | 12.5 | 0 | 0 | 0 | 0 | 0 |
| 1615 | 39 | 0 | 0 | 82.05 | 0 | 0 | 17.95 | 0 | 0 | 0 | 0 | 0 |
| 1630 | 12 | 0 | 0 | 75 | 0 | 0 | 25 | 0 | 0 | 0 | 0 | 0 |
| 1645 | 11 | 0 | 9.091 | 72.73 | 0 | 0 | 18.18 | 0 | 0 | 0 | 0 | 0 |
| 1700 | 6 | 0 | 0 | 66.67 | 0 | 16.67 | 16.67 | 0 | 0 | 0 | 0 | 0 |
| 1715 | 8 | 0 | 0 | 62.5 | 0 | 0 | 37.5 | 0 | 0 | 0 | 0 | 0 |
| 1730 | 10 | 0 | 10 | 90 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1745 | 12 | 0 | 0 | 91.67 | 0 | 0 | 8.333 | 0 | 0 | 0 | 0 | 0 |
| 1800 | 13 | 0 | 7.692 | 84.62 | 0 | 0 | 7.692 | 0 | 0 | 0 | 0 | 0 |
| 1815 | 3 | 0 | 0 | 66.67 | 0 | 0 | 33.33 | 0 | 0 | 0 | 0 | 0 |
| 1830 | 4 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1845 | 4 | 0 | 0 | 75 | 0 | 0 | 25 | 0 | 0 | 0 | 0 | 0 |
| 1900 | 3 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1915 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 1930 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1945 | 2 | 0 | 0 | 50 | 0 | 0 | 50 | 0 | 0 | 0 | 0 | 0 |
| 2000 | 3 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2015 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2030 | 2 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2045 | 3 | 0 | 0 | 66.67 | 0 | 0 | 33.33 | 0 | 0 | 0 | 0 | 0 |
| 2100 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2115 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2130 | 2 | 0 | 0 | 50 | 0 | 0 | 50 | 0 | 0 | 0 | 0 | 0 |
| 2145 | 2 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2200 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2215 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2230 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2245 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2300 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2315 | 3 | 0 | 0 | 66.67 | 0 | 0 | 33.33 | 0 | 0 | 0 | 0 | 0 |
| 2330 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2345 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2400 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 08-09 | 84 | 0 | 1.19 | 90.48 | 0 | 1.19 | 5.952 | 1.19 | 0 | 0 | 0 | 0 |
| 17-18 | 43 | 0 | 4.651 | 83.72 | 0 | 0 | 11.63 | 0 | 0 | 0 | 0 | 0 |
| 07-19 | 341 | 0 | 2.053 | 83.58 | 0 | 4.985 | 9.091 | 0.293 | 0 | 0 | 0 | 0 |
| 07-23 | 359 | 0 | 1.95 | 83.57 | 0 | 4.735 | 9.471 | 0.279 | 0 | 0 | 0 | 0 |
| 00-24 | 363 | 0 | 1.928 | 83.47 | 0 | 4.683 | 9.642 | 0.275 | 0 | 0 | 0 | 0 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
04 November 2024

| Time | Total | CI% 11 | CI% 12 | Vbin 0 5 | Vbin 5 10 | Vbin 10 15 | Vbin 15 20 | Vbin 20 25 | Vbin 25 30 | Vbin 30 35 | Vbin 35 40 | Vbin 40 45 |
|------|-------|-----------|-----------|----------------|-----------------|------------------|------------------|------------------|------------------|------------------|------------------|------------------|
| 0015 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0030 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0045 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0100 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0115 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0130 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0145 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0200 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0215 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0230 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0245 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0300 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0315 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0330 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0345 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0400 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0415 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0430 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0445 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0500 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0515 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0530 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0545 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0600 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0615 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0630 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0645 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 |
| 0700 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0715 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0730 | 3 | 0 | 0 | 0 | 0 | 1 | 2 | 0 | 0 | 0 | 0 | 0 |
| 0745 | 4 | 0 | 0 | 0 | 0 | 0 | 1 | 1 | 2 | 0 | 0 | 0 |
| 0800 | 6 | 0 | 0 | 0 | 0 | 0 | 1 | 5 | 0 | 0 | 0 | 0 |
| 0815 | 15 | 0 | 0 | 0 | 0 | 0 | 7 | 7 | 0 | 1 | 0 | 0 |
| 0830 | 35 | 0 | 0 | 0 | 1 | 1 | 9 | 20 | 3 | 1 | 0 | 0 |
| 0845 | 27 | 0 | 0 | 0 | 0 | 0 | 2 | 15 | 8 | 2 | 0 | 0 |
| 0900 | 7 | 0 | 0 | 0 | 0 | 1 | 2 | 3 | 1 | 0 | 0 | 0 |
| 0915 | 8 | 0 | 0 | 0 | 0 | 1 | 5 | 1 | 0 | 1 | 0 | 0 |
| 0930 | 2 | 0 | 0 | 0 | 0 | 0 | 1 | 1 | 0 | 0 | 0 | 0 |
| 0945 | 1 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1000 | 4 | 0 | 0 | 0 | 0 | 0 | 1 | 1 | 2 | 0 | 0 | 0 |
| 1015 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1030 | 2 | 0 | 0 | 0 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1045 | 8 | 0 | 0 | 0 | 0 | 0 | 7 | 0 | 1 | 0 | 0 | 0 |
| 1100 | 3 | 0 | 0 | 0 | 0 | 0 | 1 | 1 | 0 | 1 | 0 | 0 |
| 1115 | 6 | 0 | 0 | 0 | 0 | 0 | 2 | 2 | 1 | 1 | 0 | 0 |
| 1130 | 5 | 0 | 0 | 0 | 0 | 1 | 1 | 1 | 1 | 1 | 0 | 0 |
| 1145 | 3 | 0 | 0 | 0 | 0 | 0 | 2 | 1 | 0 | 0 | 0 | 0 |
| 1200 | 5 | 0 | 0 | 0 | 1 | 2 | 1 | 1 | 0 | 0 | 0 | 0 |
| 1215 | 2 | 0 | 0 | 0 | 0 | 1 | 0 | 1 | 0 | 0 | 0 | 0 |
| 1230 | 1 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 |
| 1245 | 4 | 0 | 0 | 0 | 0 | 1 | 1 | 1 | 1 | 0 | 0 | 0 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
04 November 2024

| Time | Total | CI% 11 | CI% 12 | Vbin 0 5 | Vbin 5 10 | Vbin 10 15 | Vbin 15 20 | Vbin 20 25 | Vbin 25 30 | Vbin 30 35 | Vbin 35 40 | Vbin 40 45 |
|--------------|------------|-----------|-----------|----------------|-----------------|------------------|------------------|------------------|------------------|------------------|------------------|------------------|
| 1300 | 6 | 0 | 0 | 0 | 0 | 2 | 0 | 3 | 1 | 0 | 0 | 0 |
| 1315 | 4 | 0 | 0 | 0 | 0 | 0 | 1 | 3 | 0 | 0 | 0 | 0 |
| 1330 | 6 | 0 | 0 | 0 | 0 | 2 | 3 | 1 | 0 | 0 | 0 | 0 |
| 1345 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 |
| 1400 | 9 | 0 | 0 | 0 | 0 | 0 | 5 | 1 | 3 | 0 | 0 | 0 |
| 1415 | 4 | 0 | 0 | 0 | 0 | 1 | 2 | 1 | 0 | 0 | 0 | 0 |
| 1430 | 1 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1445 | 4 | 0 | 0 | 0 | 0 | 0 | 1 | 3 | 0 | 0 | 0 | 0 |
| 1500 | 5 | 0 | 0 | 0 | 0 | 1 | 2 | 1 | 1 | 0 | 0 | 0 |
| 1515 | 4 | 0 | 0 | 0 | 0 | 1 | 0 | 3 | 0 | 0 | 0 | 0 |
| 1530 | 2 | 0 | 0 | 0 | 0 | 0 | 1 | 1 | 0 | 0 | 0 | 0 |
| 1545 | 11 | 0 | 0 | 1 | 0 | 3 | 5 | 0 | 1 | 1 | 0 | 0 |
| 1600 | 8 | 0 | 0 | 0 | 0 | 0 | 1 | 5 | 2 | 0 | 0 | 0 |
| 1615 | 39 | 0 | 0 | 0 | 0 | 2 | 22 | 14 | 1 | 0 | 0 | 0 |
| 1630 | 12 | 0 | 0 | 0 | 0 | 0 | 4 | 6 | 2 | 0 | 0 | 0 |
| 1645 | 11 | 0 | 0 | 0 | 0 | 0 | 5 | 6 | 0 | 0 | 0 | 0 |
| 1700 | 6 | 0 | 0 | 0 | 0 | 0 | 4 | 2 | 0 | 0 | 0 | 0 |
| 1715 | 8 | 0 | 0 | 0 | 0 | 0 | 0 | 8 | 0 | 0 | 0 | 0 |
| 1730 | 10 | 0 | 0 | 0 | 0 | 0 | 5 | 3 | 2 | 0 | 0 | 0 |
| 1745 | 12 | 0 | 0 | 0 | 0 | 0 | 1 | 10 | 1 | 0 | 0 | 0 |
| 1800 | 13 | 0 | 0 | 0 | 0 | 1 | 5 | 2 | 5 | 0 | 0 | 0 |
| 1815 | 3 | 0 | 0 | 0 | 0 | 0 | 1 | 2 | 0 | 0 | 0 | 0 |
| 1830 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 3 | 1 | 0 | 0 | 0 |
| 1845 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 3 | 0 | 0 | 0 |
| 1900 | 3 | 0 | 0 | 0 | 0 | 1 | 0 | 1 | 1 | 0 | 0 | 0 |
| 1915 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1930 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 |
| 1945 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 2 | 0 | 0 | 0 |
| 2000 | 3 | 0 | 0 | 0 | 0 | 1 | 1 | 0 | 1 | 0 | 0 | 0 |
| 2015 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2030 | 2 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 1 | 0 | 0 | 0 |
| 2045 | 3 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 2 | 0 | 0 | 0 |
| 2100 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 |
| 2115 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2130 | 2 | 0 | 0 | 0 | 0 | 0 | 1 | 1 | 0 | 0 | 0 | 0 |
| 2145 | 2 | 0 | 0 | 0 | 0 | 0 | 2 | 0 | 0 | 0 | 0 | 0 |
| 2200 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2215 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2230 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 |
| 2245 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2300 | 1 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2315 | 3 | 0 | 0 | 0 | 0 | 1 | 0 | 1 | 1 | 0 | 0 | 0 |
| 2330 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2345 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2400 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 08-09 | 84 | 0 | 0 | 0 | 1 | 2 | 20 | 45 | 12 | 4 | 0 | 0 |
| 17-18 | 43 | 0 | 0 | 0 | 0 | 1 | 11 | 23 | 8 | 0 | 0 | 0 |
| 07-19 | 341 | 0 | 0 | 1 | 2 | 27 | 115 | 143 | 44 | 9 | 0 | 0 |
| 07-23 | 359 | 0 | 0 | 1 | 2 | 30 | 120 | 147 | 50 | 9 | 0 | 0 |
| 00-24 | 363 | 0 | 0 | 1 | 2 | 31 | 120 | 148 | 52 | 9 | 0 | 0 |

Site Name - 24379-09
 Description - Cleveland Walk, East of Bathwick Hill
 Direction - West
 04 November 2024

| Time | Total | Vpp 85 | Mean | SD |
|------|-------|-----------|--------|-----|
| 0015 | 0 - | - | - | - |
| 0030 | 0 - | - | - | - |
| 0045 | 0 - | - | - | - |
| 0100 | 0 - | - | - | - |
| 0115 | 0 - | - | - | - |
| 0130 | 0 - | - | - | - |
| 0145 | 0 - | - | - | - |
| 0200 | 0 - | - | - | - |
| 0215 | 0 - | - | - | - |
| 0230 | 0 - | - | - | - |
| 0245 | 0 - | - | - | - |
| 0300 | 0 - | - | - | - |
| 0315 | 0 - | - | - | - |
| 0330 | 0 - | - | - | - |
| 0345 | 0 - | - | - | - |
| 0400 | 0 - | - | - | - |
| 0415 | 0 - | - | - | - |
| 0430 | 0 - | - | - | - |
| 0445 | 0 - | - | - | - |
| 0500 | 0 - | - | - | - |
| 0515 | 0 - | - | - | - |
| 0530 | 0 - | - | - | - |
| 0545 | 0 - | - | - | - |
| 0600 | 0 - | - | - | - |
| 0615 | 0 - | - | - | - |
| 0630 | 0 - | - | - | - |
| 0645 | 1 - | | 28.8 - | |
| 0700 | 0 - | - | - | - |
| 0715 | 0 - | - | - | - |
| 0730 | 3 - | | 17.1 | 2.5 |
| 0745 | 4 - | | 22.8 | 5.5 |
| 0800 | 6 - | | 20.8 | 1 |
| 0815 | 15 | 24 | 21.3 | 3.2 |
| 0830 | 35 | 24.9 | 21.3 | 4.1 |
| 0845 | 27 | 28.3 | 24.4 | 3.9 |
| 0900 | 7 - | | 20.1 | 4.5 |
| 0915 | 8 - | | 19.6 | 6.1 |
| 0930 | 2 - | | 18.8 | 3.8 |
| 0945 | 1 - | | 13.5 - | |
| 1000 | 4 - | | 23.5 | 5.1 |
| 1015 | 0 - | - | - | - |
| 1030 | 2 - | | 13.3 | 2.3 |
| 1045 | 8 - | | 18.8 | 3.7 |
| 1100 | 3 - | | 24 | 5.8 |
| 1115 | 6 - | | 22.8 | 6.6 |
| 1130 | 5 - | | 23 | 8.5 |
| 1145 | 3 - | | 19.3 | 2.6 |
| 1200 | 5 - | | 14.1 | 5.9 |
| 1215 | 2 - | | 18.2 | 5.1 |
| 1230 | 1 - | | 18.5 - | |
| 1245 | 4 - | | 21.3 | 6.8 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
04 November 2024

| Time | Total | Vpp 85 | Mean | SD |
|--------------|------------|-------------|-------------|------------|
| 1300 | 6 - | | 19.3 | 4.9 |
| 1315 | 4 - | | 21.1 | 2.3 |
| 1330 | 6 - | | 16.5 | 3.5 |
| 1345 | 1 - | | 23 - | |
| 1400 | 9 - | | 21 | 4.6 |
| 1415 | 4 - | | 18.9 | 4.5 |
| 1430 | 1 - | | 14.4 - | |
| 1445 | 4 - | | 20.4 | 1.7 |
| 1500 | 5 - | | 19.5 | 5.6 |
| 1515 | 4 - | | 20.6 | 5.2 |
| 1530 | 2 - | | 19.9 | 0.4 |
| 1545 | 11 | 27.6 | 17.4 | 8 |
| 1600 | 8 - | | 23.1 | 3.8 |
| 1615 | 39 | 21.8 | 19.1 | 2.8 |
| 1630 | 12 | 26.5 | 21.5 | 3 |
| 1645 | 11 | 21.3 | 19.6 | 2.1 |
| 1700 | 6 - | | 19.1 | 2.5 |
| 1715 | 8 - | | 21.2 | 1.6 |
| 1730 | 10 - | | 21.7 | 4.9 |
| 1745 | 12 | 24.9 | 22.9 | 2.5 |
| 1800 | 13 | 26.8 | 21.6 | 4.9 |
| 1815 | 3 - | | 19.8 | 0.8 |
| 1830 | 4 - | | 24.4 | 0.8 |
| 1845 | 4 - | | 25.5 | 3.5 |
| 1900 | 3 - | | 22 | 8 |
| 1915 | 0 - | | - | |
| 1930 | 1 - | | 23.2 - | |
| 1945 | 2 - | | 26.4 | 0.1 |
| 2000 | 3 - | | 20.3 | 6.1 |
| 2015 | 0 - | | - | |
| 2030 | 2 - | | 19.5 | 8.7 |
| 2045 | 3 - | | 24.1 | 6 |
| 2100 | 1 - | | 23.8 - | |
| 2115 | 0 - | | - | |
| 2130 | 2 - | | 19.6 | 4.5 |
| 2145 | 2 - | | 19.9 | 0 |
| 2200 | 0 - | | - | |
| 2215 | 0 - | | - | |
| 2230 | 1 - | | 21.6 - | |
| 2245 | 0 - | | - | |
| 2300 | 1 - | | 11.5 - | |
| 2315 | 3 - | | 21.6 | 6.9 |
| 2330 | 0 - | | - | |
| 2345 | 0 - | | - | |
| 2400 | 0 - | | - | |
| 08-09 | 84 | 25.7 | 22.2 | 4.2 |
| 17-18 | 43 | 25.3 | 21.9 | 3.8 |
| 07-19 | 341 | 25.1 | 20.8 | 4.6 |
| 07-23 | 359 | 25.3 | 20.8 | 4.6 |
| 00-24 | 363 | 25.4 | 20.8 | 4.6 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
05 November 2024

| Time | Total | Cls 1 | Cls 2 | Cls 3 | Cls 4 | Cls 5 | Cls 6 | Cls 7 | Cls 8 | Cls 9 | Cls 10 | Cls 11 |
|------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|--------|--------|
| 0015 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0030 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0045 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0115 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0130 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0145 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0200 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0215 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0230 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0245 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0300 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0315 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0330 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0345 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0400 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0415 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0430 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0445 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0500 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0515 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0530 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0545 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0600 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0615 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0630 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0645 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0700 | 2 | 0 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0715 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0730 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0745 | 3 | 1 | 1 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0800 | 7 | 0 | 5 | 0 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0815 | 18 | 0 | 16 | 0 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0830 | 24 | 0 | 21 | 0 | 1 | 2 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0845 | 23 | 0 | 22 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0900 | 15 | 0 | 12 | 0 | 1 | 2 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0915 | 6 | 1 | 3 | 0 | 1 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0930 | 7 | 0 | 6 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0945 | 3 | 0 | 2 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1000 | 6 | 0 | 6 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1015 | 8 | 0 | 6 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1030 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1045 | 2 | 0 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1100 | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1115 | 8 | 0 | 7 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1130 | 3 | 0 | 2 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1145 | 4 | 0 | 2 | 0 | 1 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1200 | 4 | 0 | 2 | 0 | 1 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1215 | 3 | 0 | 2 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1230 | 3 | 0 | 1 | 0 | 1 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1245 | 3 | 0 | 2 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Site Name - 24379-09
 Description - Cleveland Walk, East of Bathwick Hill
 Direction - West
 05 November 2024

| Time | Total | Cls 1 | Cls 2 | Cls 3 | Cls 4 | Cls 5 | Cls 6 | Cls 7 | Cls 8 | Cls 9 | Cls 10 | Cls 11 |
|--------------|------------|-----------|------------|----------|-----------|-----------|----------|----------|----------|----------|----------|----------|
| 1300 | 5 | 2 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1315 | 10 | 0 | 7 | 0 | 2 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1330 | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1345 | 7 | 1 | 4 | 0 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 |
| 1400 | 4 | 0 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1415 | 5 | 0 | 4 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1430 | 5 | 0 | 4 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1445 | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1500 | 5 | 0 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1515 | 7 | 0 | 6 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1530 | 3 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1545 | 3 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1600 | 7 | 0 | 6 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1615 | 46 | 0 | 41 | 0 | 1 | 4 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1630 | 38 | 0 | 35 | 0 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1645 | 11 | 1 | 8 | 0 | 1 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1700 | 8 | 0 | 6 | 0 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1715 | 6 | 0 | 6 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1730 | 10 | 0 | 9 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1745 | 18 | 1 | 15 | 0 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1800 | 8 | 0 | 7 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1815 | 6 | 0 | 6 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1830 | 9 | 0 | 9 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1845 | 6 | 2 | 2 | 0 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1900 | 9 | 1 | 8 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1915 | 4 | 0 | 3 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1930 | 3 | 0 | 2 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1945 | 4 | 0 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2000 | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2015 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2030 | 3 | 0 | 2 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2045 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2115 | 2 | 1 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2130 | 1 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2145 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2200 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2215 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2230 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2245 | 1 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2300 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2315 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2330 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2345 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2400 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 08-09 | 80 | 0 | 71 | 0 | 3 | 6 | 0 | 0 | 0 | 0 | 0 | 0 |
| 17-18 | 42 | 1 | 37 | 0 | 0 | 4 | 0 | 0 | 0 | 0 | 0 | 0 |
| 07-19 | 395 | 10 | 329 | 0 | 20 | 35 | 1 | 0 | 0 | 0 | 0 | 0 |
| 07-23 | 417 | 11 | 344 | 0 | 20 | 41 | 1 | 0 | 0 | 0 | 0 | 0 |
| 00-24 | 422 | 11 | 348 | 0 | 21 | 41 | 1 | 0 | 0 | 0 | 0 | 0 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
05 November 2024

| Time | Total | Cls 12 | CI% 1 | CI% 2 | CI% 3 | CI% 4 | CI% 5 | CI% 6 | CI% 7 | CI% 8 | CI% 9 | CI% 10 |
|------|-------|-----------|----------|----------|----------|----------|----------|----------|----------|----------|----------|-----------|
| 0015 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0030 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0045 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0100 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0115 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0130 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0145 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0200 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0215 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0230 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0245 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0300 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0315 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0330 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0345 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0400 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0415 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0430 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0445 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0500 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0515 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0530 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0545 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0600 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0615 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0630 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0645 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0700 | 2 | 0 | 0 | 50 | 0 | 50 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0715 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0730 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0745 | 3 | 0 | 33.33 | 33.33 | 0 | 0 | 33.33 | 0 | 0 | 0 | 0 | 0 |
| 0800 | 7 | 0 | 0 | 71.43 | 0 | 0 | 28.57 | 0 | 0 | 0 | 0 | 0 |
| 0815 | 18 | 0 | 0 | 88.89 | 0 | 0 | 11.11 | 0 | 0 | 0 | 0 | 0 |
| 0830 | 24 | 0 | 0 | 87.5 | 0 | 4.167 | 8.333 | 0 | 0 | 0 | 0 | 0 |
| 0845 | 23 | 0 | 0 | 95.65 | 0 | 4.348 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0900 | 15 | 0 | 0 | 80 | 0 | 6.667 | 13.33 | 0 | 0 | 0 | 0 | 0 |
| 0915 | 6 | 0 | 16.67 | 50 | 0 | 16.67 | 16.67 | 0 | 0 | 0 | 0 | 0 |
| 0930 | 7 | 0 | 0 | 85.71 | 0 | 0 | 14.29 | 0 | 0 | 0 | 0 | 0 |
| 0945 | 3 | 0 | 0 | 66.67 | 0 | 33.33 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1000 | 6 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1015 | 8 | 0 | 0 | 75 | 0 | 25 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1030 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1045 | 2 | 0 | 0 | 50 | 0 | 50 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1100 | 2 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1115 | 8 | 0 | 0 | 87.5 | 0 | 12.5 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1130 | 3 | 0 | 0 | 66.67 | 0 | 33.33 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1145 | 4 | 0 | 0 | 50 | 0 | 25 | 25 | 0 | 0 | 0 | 0 | 0 |
| 1200 | 4 | 0 | 0 | 50 | 0 | 25 | 25 | 0 | 0 | 0 | 0 | 0 |
| 1215 | 3 | 0 | 0 | 66.67 | 0 | 0 | 33.33 | 0 | 0 | 0 | 0 | 0 |
| 1230 | 3 | 0 | 0 | 33.33 | 0 | 33.33 | 33.33 | 0 | 0 | 0 | 0 | 0 |
| 1245 | 3 | 0 | 0 | 66.67 | 0 | 33.33 | 0 | 0 | 0 | 0 | 0 | 0 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
05 November 2024

| Time | Total | Cls 12 | CI% 1 | CI% 2 | CI% 3 | CI% 4 | CI% 5 | CI% 6 | CI% 7 | CI% 8 | CI% 9 | CI% 10 |
|--------------|------------|-----------|--------------|--------------|----------|--------------|--------------|--------------|----------|----------|----------|-----------|
| 1300 | 5 | 0 | 40 | 60 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1315 | 10 | 0 | 0 | 70 | 0 | 20 | 10 | 0 | 0 | 0 | 0 | 0 |
| 1330 | 2 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1345 | 7 | 0 | 14.29 | 57.14 | 0 | 14.29 | 0 | 14.29 | 0 | 0 | 0 | 0 |
| 1400 | 4 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1415 | 5 | 0 | 0 | 80 | 0 | 20 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1430 | 5 | 0 | 0 | 80 | 0 | 0 | 20 | 0 | 0 | 0 | 0 | 0 |
| 1445 | 2 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1500 | 5 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1515 | 7 | 0 | 0 | 85.71 | 0 | 0 | 14.29 | 0 | 0 | 0 | 0 | 0 |
| 1530 | 3 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1545 | 3 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1600 | 7 | 0 | 0 | 85.71 | 0 | 0 | 14.29 | 0 | 0 | 0 | 0 | 0 |
| 1615 | 46 | 0 | 0 | 89.13 | 0 | 2.174 | 8.696 | 0 | 0 | 0 | 0 | 0 |
| 1630 | 38 | 0 | 0 | 92.11 | 0 | 0 | 7.895 | 0 | 0 | 0 | 0 | 0 |
| 1645 | 11 | 0 | 9.091 | 72.73 | 0 | 9.091 | 9.091 | 0 | 0 | 0 | 0 | 0 |
| 1700 | 8 | 0 | 0 | 75 | 0 | 0 | 25 | 0 | 0 | 0 | 0 | 0 |
| 1715 | 6 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1730 | 10 | 0 | 0 | 90 | 0 | 0 | 10 | 0 | 0 | 0 | 0 | 0 |
| 1745 | 18 | 0 | 5.556 | 83.33 | 0 | 0 | 11.11 | 0 | 0 | 0 | 0 | 0 |
| 1800 | 8 | 0 | 0 | 87.5 | 0 | 0 | 12.5 | 0 | 0 | 0 | 0 | 0 |
| 1815 | 6 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1830 | 9 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1845 | 6 | 0 | 33.33 | 33.33 | 0 | 0 | 33.33 | 0 | 0 | 0 | 0 | 0 |
| 1900 | 9 | 0 | 11.11 | 88.89 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1915 | 4 | 0 | 0 | 75 | 0 | 0 | 25 | 0 | 0 | 0 | 0 | 0 |
| 1930 | 3 | 0 | 0 | 66.67 | 0 | 0 | 33.33 | 0 | 0 | 0 | 0 | 0 |
| 1945 | 4 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2000 | 2 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2015 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2030 | 3 | 0 | 0 | 66.67 | 0 | 0 | 33.33 | 0 | 0 | 0 | 0 | 0 |
| 2045 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2100 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2115 | 2 | 0 | 50 | 0 | 0 | 0 | 50 | 0 | 0 | 0 | 0 | 0 |
| 2130 | 1 | 0 | 0 | 0 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 |
| 2145 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2200 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2215 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2230 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2245 | 1 | 0 | 0 | 0 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 |
| 2300 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2315 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2330 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2345 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2400 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 08-09 | 80 | 0 | 0 | 88.75 | 0 | 3.75 | 7.5 | 0 | 0 | 0 | 0 | 0 |
| 17-18 | 42 | 0 | 2.381 | 88.1 | 0 | 0 | 9.524 | 0 | 0 | 0 | 0 | 0 |
| 07-19 | 395 | 0 | 2.532 | 83.29 | 0 | 5.063 | 8.861 | 0.253 | 0 | 0 | 0 | 0 |
| 07-23 | 417 | 0 | 2.638 | 82.49 | 0 | 4.796 | 9.832 | 0.24 | 0 | 0 | 0 | 0 |
| 00-24 | 422 | 0 | 2.607 | 82.46 | 0 | 4.976 | 9.716 | 0.237 | 0 | 0 | 0 | 0 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
05 November 2024

| Time | Total | CI% 11 | CI% 12 | Vbin 0 5 | Vbin 5 10 | Vbin 10 15 | Vbin 15 20 | Vbin 20 25 | Vbin 25 30 | Vbin 30 35 | Vbin 35 40 | Vbin 40 45 |
|------|-------|-----------|-----------|----------------|-----------------|------------------|------------------|------------------|------------------|------------------|------------------|------------------|
| 0015 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0030 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0045 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0100 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0115 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0130 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0145 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0200 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0215 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0230 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0245 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0300 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0315 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0330 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0345 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0400 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0415 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0430 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0445 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0500 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0515 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0530 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0545 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0600 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0615 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0630 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0645 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 |
| 0700 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 1 | 0 | 0 |
| 0715 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 |
| 0730 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 |
| 0745 | 3 | 0 | 0 | 0 | 0 | 1 | 1 | 1 | 0 | 0 | 0 | 0 |
| 0800 | 7 | 0 | 0 | 0 | 0 | 0 | 5 | 2 | 0 | 0 | 0 | 0 |
| 0815 | 18 | 0 | 0 | 0 | 0 | 0 | 8 | 7 | 3 | 0 | 0 | 0 |
| 0830 | 24 | 0 | 0 | 0 | 0 | 0 | 4 | 18 | 2 | 0 | 0 | 0 |
| 0845 | 23 | 0 | 0 | 0 | 0 | 0 | 11 | 9 | 3 | 0 | 0 | 0 |
| 0900 | 15 | 0 | 0 | 0 | 0 | 0 | 6 | 6 | 3 | 0 | 0 | 0 |
| 0915 | 6 | 0 | 0 | 0 | 0 | 1 | 3 | 1 | 1 | 0 | 0 | 0 |
| 0930 | 7 | 0 | 0 | 0 | 0 | 1 | 0 | 4 | 2 | 0 | 0 | 0 |
| 0945 | 3 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 2 | 0 | 0 | 0 |
| 1000 | 6 | 0 | 0 | 0 | 0 | 0 | 2 | 3 | 1 | 0 | 0 | 0 |
| 1015 | 8 | 0 | 0 | 0 | 0 | 0 | 2 | 4 | 2 | 0 | 0 | 0 |
| 1030 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 |
| 1045 | 2 | 0 | 0 | 0 | 0 | 1 | 1 | 0 | 0 | 0 | 0 | 0 |
| 1100 | 2 | 0 | 0 | 0 | 0 | 1 | 0 | 1 | 0 | 0 | 0 | 0 |
| 1115 | 8 | 0 | 0 | 0 | 1 | 1 | 4 | 1 | 0 | 1 | 0 | 0 |
| 1130 | 3 | 0 | 0 | 0 | 0 | 1 | 0 | 1 | 1 | 0 | 0 | 0 |
| 1145 | 4 | 0 | 0 | 0 | 0 | 0 | 3 | 1 | 0 | 0 | 0 | 0 |
| 1200 | 4 | 0 | 0 | 0 | 1 | 0 | 3 | 0 | 0 | 0 | 0 | 0 |
| 1215 | 3 | 0 | 0 | 0 | 0 | 1 | 1 | 1 | 0 | 0 | 0 | 0 |
| 1230 | 3 | 0 | 0 | 0 | 0 | 2 | 1 | 0 | 0 | 0 | 0 | 0 |
| 1245 | 3 | 0 | 0 | 0 | 0 | 1 | 1 | 0 | 0 | 1 | 0 | 0 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
05 November 2024

| Time | Total | CI% 11 | CI% 12 | Vbin 0 5 | Vbin 5 10 | Vbin 10 15 | Vbin 15 20 | Vbin 20 25 | Vbin 25 30 | Vbin 30 35 | Vbin 35 40 | Vbin 40 45 |
|--------------|------------|-----------|-----------|----------------|-----------------|------------------|------------------|------------------|------------------|------------------|------------------|------------------|
| 1300 | 5 | 0 | 0 | 0 | 0 | 1 | 1 | 2 | 1 | 0 | 0 | 0 |
| 1315 | 10 | 0 | 0 | 0 | 0 | 0 | 7 | 3 | 0 | 0 | 0 | 0 |
| 1330 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 1 | 0 | 0 | 0 |
| 1345 | 7 | 0 | 0 | 0 | 0 | 0 | 6 | 0 | 1 | 0 | 0 | 0 |
| 1400 | 4 | 0 | 0 | 0 | 0 | 4 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1415 | 5 | 0 | 0 | 0 | 0 | 0 | 5 | 0 | 0 | 0 | 0 | 0 |
| 1430 | 5 | 0 | 0 | 0 | 0 | 1 | 0 | 3 | 0 | 1 | 0 | 0 |
| 1445 | 2 | 0 | 0 | 0 | 0 | 0 | 1 | 1 | 0 | 0 | 0 | 0 |
| 1500 | 5 | 0 | 0 | 0 | 0 | 0 | 3 | 1 | 1 | 0 | 0 | 0 |
| 1515 | 7 | 0 | 0 | 0 | 0 | 1 | 2 | 4 | 0 | 0 | 0 | 0 |
| 1530 | 3 | 0 | 0 | 0 | 0 | 0 | 2 | 0 | 1 | 0 | 0 | 0 |
| 1545 | 3 | 0 | 0 | 0 | 0 | 0 | 2 | 1 | 0 | 0 | 0 | 0 |
| 1600 | 7 | 0 | 0 | 0 | 1 | 0 | 0 | 6 | 0 | 0 | 0 | 0 |
| 1615 | 46 | 0 | 0 | 0 | 1 | 9 | 27 | 9 | 0 | 0 | 0 | 0 |
| 1630 | 38 | 0 | 0 | 0 | 0 | 2 | 22 | 13 | 1 | 0 | 0 | 0 |
| 1645 | 11 | 0 | 0 | 0 | 0 | 2 | 1 | 7 | 1 | 0 | 0 | 0 |
| 1700 | 8 | 0 | 0 | 0 | 0 | 0 | 0 | 3 | 5 | 0 | 0 | 0 |
| 1715 | 6 | 0 | 0 | 0 | 0 | 0 | 0 | 3 | 3 | 0 | 0 | 0 |
| 1730 | 10 | 0 | 0 | 0 | 0 | 0 | 2 | 7 | 1 | 0 | 0 | 0 |
| 1745 | 18 | 0 | 0 | 0 | 0 | 1 | 5 | 8 | 3 | 1 | 0 | 0 |
| 1800 | 8 | 0 | 0 | 0 | 0 | 0 | 0 | 5 | 2 | 1 | 0 | 0 |
| 1815 | 6 | 0 | 0 | 0 | 0 | 0 | 2 | 3 | 1 | 0 | 0 | 0 |
| 1830 | 9 | 0 | 0 | 0 | 0 | 0 | 2 | 5 | 2 | 0 | 0 | 0 |
| 1845 | 6 | 0 | 0 | 0 | 0 | 2 | 1 | 1 | 2 | 0 | 0 | 0 |
| 1900 | 9 | 0 | 0 | 1 | 0 | 0 | 1 | 4 | 3 | 0 | 0 | 0 |
| 1915 | 4 | 0 | 0 | 0 | 0 | 1 | 2 | 1 | 0 | 0 | 0 | 0 |
| 1930 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 3 | 0 | 0 | 0 |
| 1945 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 2 | 2 | 0 | 0 | 0 |
| 2000 | 2 | 0 | 0 | 0 | 0 | 0 | 1 | 1 | 0 | 0 | 0 | 0 |
| 2015 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 |
| 2030 | 3 | 0 | 0 | 0 | 0 | 0 | 1 | 2 | 0 | 0 | 0 | 0 |
| 2045 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2100 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2115 | 2 | 0 | 0 | 0 | 0 | 0 | 1 | 1 | 0 | 0 | 0 | 0 |
| 2130 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 |
| 2145 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2200 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2215 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2230 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2245 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 |
| 2300 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2315 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 |
| 2330 | 1 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2345 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2400 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 08-09 | 80 | 0 | 0 | 0 | 0 | 0 | 29 | 40 | 11 | 0 | 0 | 0 |
| 17-18 | 42 | 0 | 0 | 0 | 0 | 1 | 7 | 23 | 9 | 2 | 0 | 0 |
| 07-19 | 395 | 0 | 0 | 1 | 4 | 34 | 149 | 152 | 50 | 5 | 0 | 0 |
| 07-23 | 417 | 0 | 0 | 1 | 4 | 35 | 154 | 161 | 55 | 6 | 0 | 0 |
| 00-24 | 422 | 0 | 0 | 1 | 4 | 36 | 154 | 162 | 55 | 9 | 0 | 0 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
05 November 2024

| Time | Total | Vpp 85 | Mean | SD |
|------|-------|-----------|--------|-----|
| 0015 | 0 - | - | - | - |
| 0030 | 0 - | - | - | - |
| 0045 | 0 - | - | - | - |
| 0100 | 0 - | - | - | - |
| 0115 | 0 - | - | - | - |
| 0130 | 0 - | - | - | - |
| 0145 | 0 - | - | - | - |
| 0200 | 0 - | - | - | - |
| 0215 | 0 - | - | - | - |
| 0230 | 0 - | - | - | - |
| 0245 | 0 - | - | - | - |
| 0300 | 0 - | - | - | - |
| 0315 | 0 - | - | - | - |
| 0330 | 0 - | - | - | - |
| 0345 | 0 - | - | - | - |
| 0400 | 0 - | - | - | - |
| 0415 | 0 - | - | - | - |
| 0430 | 0 - | - | - | - |
| 0445 | 0 - | - | - | - |
| 0500 | 0 - | - | - | - |
| 0515 | 0 - | - | - | - |
| 0530 | 0 - | - | - | - |
| 0545 | 0 - | - | - | - |
| 0600 | 0 - | - | - | - |
| 0615 | 0 - | - | - | - |
| 0630 | 0 - | - | - | - |
| 0645 | 1 - | | 30.5 - | |
| 0700 | 2 - | | 27.5 | 7.7 |
| 0715 | 1 - | | 23.6 - | |
| 0730 | 1 - | | 24.4 - | |
| 0745 | 3 - | | 17.7 | 5.1 |
| 0800 | 7 - | | 18.8 | 1.2 |
| 0815 | 18 | 25.8 | 20.9 | 2.8 |
| 0830 | 24 | 23.6 | 21.8 | 1.9 |
| 0845 | 23 | 24.9 | 20.6 | 3.5 |
| 0900 | 15 | 25.4 | 21.3 | 3 |
| 0915 | 6 - | | 20 | 4.6 |
| 0930 | 7 - | | 23.3 | 4.7 |
| 0945 | 3 - | | 23.8 | 5.8 |
| 1000 | 6 - | | 20.9 | 4.3 |
| 1015 | 8 - | | 22.5 | 3.5 |
| 1030 | 1 - | | 26.1 - | |
| 1045 | 2 - | | 15.2 | 1.5 |
| 1100 | 2 - | | 17.3 | 4 |
| 1115 | 8 - | | 18.6 | 7.8 |
| 1130 | 3 - | | 21 | 6.7 |
| 1145 | 4 - | | 18.6 | 2 |
| 1200 | 4 - | | 16.4 | 6.7 |
| 1215 | 3 - | | 18.7 | 5.3 |
| 1230 | 3 - | | 15 | 3.3 |
| 1245 | 3 - | | 21.3 | 8.3 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
05 November 2024

| Time | Total | Vpp 85 | Mean | SD |
|--------------|------------|-------------|-------------|------------|
| 1300 | 5 - | | 20.6 | 6.5 |
| 1315 | 10 - | | 19.3 | 1.1 |
| 1330 | 2 - | | 25.7 | 3.2 |
| 1345 | 7 - | | 19.8 | 3.6 |
| 1400 | 4 - | | 13.7 | 0.8 |
| 1415 | 5 - | | 16.8 | 1.1 |
| 1430 | 5 - | | 22.6 | 7.3 |
| 1445 | 2 - | | 19.9 | 5.5 |
| 1500 | 5 - | | 20.7 | 5.2 |
| 1515 | 7 - | | 18.3 | 4.1 |
| 1530 | 3 - | | 19.6 | 6.3 |
| 1545 | 3 - | | 18.9 | 3.4 |
| 1600 | 7 - | | 20 | 5.5 |
| 1615 | 46 | 20.2 | 17.3 | 3.3 |
| 1630 | 38 | 22.2 | 19.1 | 3.1 |
| 1645 | 11 | 25.4 | 21.5 | 4.6 |
| 1700 | 8 - | | 25.7 | 2.7 |
| 1715 | 6 - | | 25.6 | 2.6 |
| 1730 | 10 - | | 22.6 | 2.7 |
| 1745 | 18 | 27.9 | 22.4 | 5.1 |
| 1800 | 8 - | | 25.5 | 4.3 |
| 1815 | 6 - | | 22 | 3.8 |
| 1830 | 9 - | | 22.8 | 3.5 |
| 1845 | 6 - | | 19.4 | 6.7 |
| 1900 | 9 - | | 21.4 | 7.5 |
| 1915 | 4 - | | 17.7 | 2.3 |
| 1930 | 3 - | | 26.5 | 1.2 |
| 1945 | 4 - | | 26 | 1.6 |
| 2000 | 2 - | | 20.4 | 2.6 |
| 2015 | 1 - | | 22.3 - | |
| 2030 | 3 - | | 20.5 | 3 |
| 2045 | 0 - | - | - | |
| 2100 | 0 - | - | - | |
| 2115 | 2 - | | 19.8 | 2.8 |
| 2130 | 1 - | | 20.7 - | |
| 2145 | 0 - | - | - | |
| 2200 | 0 - | - | - | |
| 2215 | 1 - | | 47.5 - | |
| 2230 | 0 - | - | - | |
| 2245 | 1 - | | 30.7 - | |
| 2300 | 0 - | - | - | |
| 2315 | 1 - | | 32.3 - | |
| 2330 | 1 - | | 13 - | |
| 2345 | 0 - | - | - | |
| 2400 | 0 - | - | - | |
| 08-09 | 80 | 24.5 | 21.2 | 2.8 |
| 17-18 | 42 | 28 | 23.5 | 4.3 |
| 07-19 | 395 | 24.7 | 20.4 | 4.5 |
| 07-23 | 417 | 25 | 20.6 | 4.7 |
| 00-24 | 422 | 25.1 | 20.6 | 4.8 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
06 November 2024

| Time | Total | Cls 1 | Cls 2 | Cls 3 | Cls 4 | Cls 5 | Cls 6 | Cls 7 | Cls 8 | Cls 9 | Cls 10 | Cls 11 |
|------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|--------|--------|
| 0015 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0030 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0045 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0100 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0115 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0130 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0145 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0200 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0215 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0230 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0245 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0300 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0315 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0330 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0345 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0400 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0415 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0430 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0445 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0500 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0515 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0530 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0545 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0600 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0615 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0630 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0645 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0700 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0715 | 4 | 0 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0730 | 6 | 1 | 4 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0745 | 1 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0800 | 8 | 0 | 6 | 0 | 0 | 1 | 1 | 0 | 0 | 0 | 0 | 0 |
| 0815 | 23 | 0 | 19 | 0 | 2 | 2 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0830 | 20 | 0 | 17 | 0 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0845 | 23 | 0 | 19 | 0 | 2 | 1 | 1 | 0 | 0 | 0 | 0 | 0 |
| 0900 | 10 | 1 | 9 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0915 | 3 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0930 | 8 | 0 | 7 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0945 | 2 | 0 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1000 | 7 | 0 | 6 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1015 | 12 | 0 | 10 | 0 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1030 | 5 | 0 | 4 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1045 | 6 | 0 | 3 | 0 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1115 | 5 | 0 | 2 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1130 | 5 | 0 | 4 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1145 | 4 | 0 | 3 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1200 | 7 | 1 | 5 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1215 | 7 | 0 | 2 | 0 | 3 | 2 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1230 | 3 | 0 | 2 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1245 | 5 | 0 | 4 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
06 November 2024

| Time | Total | Cls 1 | Cls 2 | Cls 3 | Cls 4 | Cls 5 | Cls 6 | Cls 7 | Cls 8 | Cls 9 | Cls 10 | Cls 11 |
|--------------|------------|-----------|------------|----------|-----------|-----------|----------|----------|----------|----------|----------|----------|
| 1300 | 2 | 0 | 1 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1315 | 4 | 1 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1330 | 8 | 1 | 6 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1345 | 3 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1400 | 8 | 0 | 6 | 0 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1415 | 6 | 0 | 6 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1430 | 7 | 0 | 4 | 0 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1445 | 5 | 0 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1500 | 4 | 0 | 3 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1515 | 5 | 0 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1530 | 3 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1545 | 6 | 2 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1600 | 10 | 0 | 9 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1615 | 44 | 0 | 38 | 0 | 2 | 4 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1630 | 31 | 0 | 27 | 0 | 1 | 3 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1645 | 10 | 0 | 9 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1700 | 3 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1715 | 9 | 1 | 7 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1730 | 11 | 1 | 8 | 0 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1745 | 14 | 2 | 10 | 0 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1800 | 5 | 1 | 3 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 |
| 1815 | 16 | 1 | 12 | 0 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1830 | 14 | 0 | 12 | 0 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1845 | 7 | 0 | 7 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1900 | 3 | 1 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1915 | 3 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1930 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1945 | 3 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2000 | 8 | 1 | 7 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2015 | 2 | 0 | 1 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2030 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2045 | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2115 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2130 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2145 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2200 | 1 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2215 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2230 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2245 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2300 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2315 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2330 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2345 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2400 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 08-09 | 76 | 1 | 64 | 0 | 4 | 6 | 1 | 0 | 0 | 0 | 0 | 0 |
| 17-18 | 39 | 5 | 28 | 0 | 0 | 5 | 1 | 0 | 0 | 0 | 0 | 0 |
| 07-19 | 412 | 14 | 330 | 0 | 22 | 43 | 3 | 0 | 0 | 0 | 0 | 0 |
| 07-23 | 436 | 15 | 351 | 0 | 22 | 45 | 3 | 0 | 0 | 0 | 0 | 0 |
| 00-24 | 441 | 15 | 356 | 0 | 22 | 45 | 3 | 0 | 0 | 0 | 0 | 0 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
06 November 2024

| Time | Total | Cls 12 | CI% 1 | CI% 2 | CI% 3 | CI% 4 | CI% 5 | CI% 6 | CI% 7 | CI% 8 | CI% 9 | CI% 10 |
|------|-------|-----------|----------|----------|----------|----------|----------|----------|----------|----------|----------|-----------|
| 0015 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0030 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0045 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0100 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0115 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0130 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0145 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0200 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0215 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0230 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0245 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0300 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0315 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0330 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0345 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0400 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0415 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0430 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0445 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0500 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0515 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0530 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0545 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0600 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0615 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0630 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0645 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0700 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0715 | 4 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0730 | 6 | 0 | 16.67 | 66.67 | 0 | 16.67 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0745 | 1 | 0 | 0 | 0 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 |
| 0800 | 8 | 0 | 0 | 75 | 0 | 0 | 12.5 | 12.5 | 0 | 0 | 0 | 0 |
| 0815 | 23 | 0 | 0 | 82.61 | 0 | 8.696 | 8.696 | 0 | 0 | 0 | 0 | 0 |
| 0830 | 20 | 0 | 0 | 85 | 0 | 0 | 15 | 0 | 0 | 0 | 0 | 0 |
| 0845 | 23 | 0 | 0 | 82.61 | 0 | 8.696 | 4.348 | 4.348 | 0 | 0 | 0 | 0 |
| 0900 | 10 | 0 | 10 | 90 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0915 | 3 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0930 | 8 | 0 | 0 | 87.5 | 0 | 0 | 12.5 | 0 | 0 | 0 | 0 | 0 |
| 0945 | 2 | 0 | 0 | 50 | 0 | 50 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1000 | 7 | 0 | 0 | 85.71 | 0 | 14.29 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1015 | 12 | 0 | 0 | 83.33 | 0 | 0 | 16.67 | 0 | 0 | 0 | 0 | 0 |
| 1030 | 5 | 0 | 0 | 80 | 0 | 0 | 20 | 0 | 0 | 0 | 0 | 0 |
| 1045 | 6 | 0 | 0 | 50 | 0 | 0 | 50 | 0 | 0 | 0 | 0 | 0 |
| 1100 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 1115 | 5 | 0 | 0 | 40 | 0 | 60 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1130 | 5 | 0 | 0 | 80 | 0 | 20 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1145 | 4 | 0 | 0 | 75 | 0 | 25 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1200 | 7 | 0 | 14.29 | 71.43 | 0 | 0 | 14.29 | 0 | 0 | 0 | 0 | 0 |
| 1215 | 7 | 0 | 0 | 28.57 | 0 | 42.86 | 28.57 | 0 | 0 | 0 | 0 | 0 |
| 1230 | 3 | 0 | 0 | 66.67 | 0 | 33.33 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1245 | 5 | 0 | 0 | 80 | 0 | 20 | 0 | 0 | 0 | 0 | 0 | 0 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
06 November 2024

| Time | Total | Cls 12 | CI% 1 | CI% 2 | CI% 3 | CI% 4 | CI% 5 | CI% 6 | CI% 7 | CI% 8 | CI% 9 | CI% 10 |
|--------------|------------|-----------|--------------|--------------|----------|--------------|--------------|--------------|----------|----------|----------|-----------|
| 1300 | 2 | 0 | 0 | 50 | 0 | 0 | 50 | 0 | 0 | 0 | 0 | 0 |
| 1315 | 4 | 0 | 25 | 75 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1330 | 8 | 0 | 12.5 | 75 | 0 | 12.5 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1345 | 3 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1400 | 8 | 0 | 0 | 75 | 0 | 0 | 25 | 0 | 0 | 0 | 0 | 0 |
| 1415 | 6 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1430 | 7 | 0 | 0 | 57.14 | 0 | 0 | 42.86 | 0 | 0 | 0 | 0 | 0 |
| 1445 | 5 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1500 | 4 | 0 | 0 | 75 | 0 | 25 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1515 | 5 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1530 | 3 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1545 | 6 | 0 | 33.33 | 66.67 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1600 | 10 | 0 | 0 | 90 | 0 | 0 | 10 | 0 | 0 | 0 | 0 | 0 |
| 1615 | 44 | 0 | 0 | 86.36 | 0 | 4.545 | 9.091 | 0 | 0 | 0 | 0 | 0 |
| 1630 | 31 | 0 | 0 | 87.1 | 0 | 3.226 | 9.677 | 0 | 0 | 0 | 0 | 0 |
| 1645 | 10 | 0 | 0 | 90 | 0 | 0 | 10 | 0 | 0 | 0 | 0 | 0 |
| 1700 | 3 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1715 | 9 | 0 | 11.11 | 77.78 | 0 | 0 | 11.11 | 0 | 0 | 0 | 0 | 0 |
| 1730 | 11 | 0 | 9.091 | 72.73 | 0 | 0 | 18.18 | 0 | 0 | 0 | 0 | 0 |
| 1745 | 14 | 0 | 14.29 | 71.43 | 0 | 0 | 14.29 | 0 | 0 | 0 | 0 | 0 |
| 1800 | 5 | 0 | 20 | 60 | 0 | 0 | 0 | 20 | 0 | 0 | 0 | 0 |
| 1815 | 16 | 0 | 6.25 | 75 | 0 | 0 | 18.75 | 0 | 0 | 0 | 0 | 0 |
| 1830 | 14 | 0 | 0 | 85.71 | 0 | 0 | 14.29 | 0 | 0 | 0 | 0 | 0 |
| 1845 | 7 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1900 | 3 | 0 | 33.33 | 66.67 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1915 | 3 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1930 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1945 | 3 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2000 | 8 | 0 | 12.5 | 87.5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2015 | 2 | 0 | 0 | 50 | 0 | 0 | 50 | 0 | 0 | 0 | 0 | 0 |
| 2030 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2045 | 2 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2100 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2115 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2130 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2145 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2200 | 1 | 0 | 0 | 0 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 |
| 2215 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2230 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2245 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2300 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2315 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2330 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2345 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2400 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 08-09 | 76 | 0 | 1.316 | 84.21 | 0 | 5.263 | 7.895 | 1.316 | 0 | 0 | 0 | 0 |
| 17-18 | 39 | 0 | 12.82 | 71.79 | 0 | 0 | 12.82 | 2.564 | 0 | 0 | 0 | 0 |
| 07-19 | 412 | 0 | 3.398 | 80.1 | 0 | 5.34 | 10.44 | 0.728 | 0 | 0 | 0 | 0 |
| 07-23 | 436 | 0 | 3.44 | 80.5 | 0 | 5.046 | 10.32 | 0.688 | 0 | 0 | 0 | 0 |
| 00-24 | 441 | 0 | 3.401 | 80.73 | 0 | 4.989 | 10.2 | 0.68 | 0 | 0 | 0 | 0 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
06 November 2024

| Time | Total | CI% 11 | CI% 12 | Vbin 0 5 | Vbin 5 10 | Vbin 10 15 | Vbin 15 20 | Vbin 20 25 | Vbin 25 30 | Vbin 30 35 | Vbin 35 40 | Vbin 40 45 |
|------|-------|-----------|-----------|----------------|-----------------|------------------|------------------|------------------|------------------|------------------|------------------|------------------|
| 0015 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0030 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0045 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0100 | 1 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0115 | 1 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 |
| 0130 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0145 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0200 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0215 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0230 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0245 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0300 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0315 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0330 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0345 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0400 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0415 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0430 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0445 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0500 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0515 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0530 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0545 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0600 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0615 | 1 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 |
| 0630 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0645 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 |
| 0700 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 |
| 0715 | 4 | 0 | 0 | 0 | 0 | 1 | 2 | 1 | 0 | 0 | 0 | 0 |
| 0730 | 6 | 0 | 0 | 0 | 0 | 1 | 1 | 4 | 0 | 0 | 0 | 0 |
| 0745 | 1 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 |
| 0800 | 8 | 0 | 0 | 0 | 0 | 0 | 1 | 7 | 0 | 0 | 0 | 0 |
| 0815 | 23 | 0 | 0 | 0 | 0 | 0 | 2 | 14 | 7 | 0 | 0 | 0 |
| 0830 | 20 | 0 | 0 | 0 | 0 | 0 | 5 | 12 | 2 | 1 | 0 | 0 |
| 0845 | 23 | 0 | 0 | 0 | 0 | 0 | 6 | 11 | 6 | 0 | 0 | 0 |
| 0900 | 10 | 0 | 0 | 0 | 0 | 2 | 2 | 4 | 2 | 0 | 0 | 0 |
| 0915 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 2 | 0 | 0 | 0 |
| 0930 | 8 | 0 | 0 | 0 | 0 | 2 | 3 | 3 | 0 | 0 | 0 | 0 |
| 0945 | 2 | 0 | 0 | 0 | 0 | 0 | 2 | 0 | 0 | 0 | 0 | 0 |
| 1000 | 7 | 0 | 0 | 0 | 0 | 1 | 3 | 2 | 1 | 0 | 0 | 0 |
| 1015 | 12 | 0 | 0 | 0 | 1 | 1 | 3 | 7 | 0 | 0 | 0 | 0 |
| 1030 | 5 | 0 | 0 | 0 | 0 | 1 | 0 | 2 | 2 | 0 | 0 | 0 |
| 1045 | 6 | 0 | 0 | 0 | 0 | 0 | 4 | 2 | 0 | 0 | 0 | 0 |
| 1100 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1115 | 5 | 0 | 0 | 0 | 0 | 1 | 2 | 2 | 0 | 0 | 0 | 0 |
| 1130 | 5 | 0 | 0 | 0 | 0 | 2 | 2 | 1 | 0 | 0 | 0 | 0 |
| 1145 | 4 | 0 | 0 | 0 | 0 | 0 | 3 | 0 | 1 | 0 | 0 | 0 |
| 1200 | 7 | 0 | 0 | 0 | 0 | 1 | 2 | 3 | 1 | 0 | 0 | 0 |
| 1215 | 7 | 0 | 0 | 0 | 1 | 1 | 3 | 1 | 1 | 0 | 0 | 0 |
| 1230 | 3 | 0 | 0 | 0 | 0 | 2 | 1 | 0 | 0 | 0 | 0 | 0 |
| 1245 | 5 | 0 | 0 | 0 | 0 | 1 | 4 | 0 | 0 | 0 | 0 | 0 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
06 November 2024

| Time | Total | CI% 11 | CI% 12 | Vbin 0 5 | Vbin 5 10 | Vbin 10 15 | Vbin 15 20 | Vbin 20 25 | Vbin 25 30 | Vbin 30 35 | Vbin 35 40 | Vbin 40 45 |
|--------------|------------|-----------|-----------|----------------|-----------------|------------------|------------------|------------------|------------------|------------------|------------------|------------------|
| 1300 | 2 | 0 | 0 | 0 | 0 | 0 | 1 | 1 | 0 | 0 | 0 | 0 |
| 1315 | 4 | 0 | 0 | 0 | 0 | 0 | 3 | 1 | 0 | 0 | 0 | 0 |
| 1330 | 8 | 0 | 0 | 0 | 1 | 1 | 2 | 2 | 2 | 0 | 0 | 0 |
| 1345 | 3 | 0 | 0 | 0 | 0 | 0 | 1 | 1 | 1 | 0 | 0 | 0 |
| 1400 | 8 | 0 | 0 | 0 | 1 | 1 | 2 | 3 | 1 | 0 | 0 | 0 |
| 1415 | 6 | 0 | 0 | 0 | 0 | 0 | 2 | 3 | 1 | 0 | 0 | 0 |
| 1430 | 7 | 0 | 0 | 0 | 0 | 0 | 4 | 2 | 0 | 1 | 0 | 0 |
| 1445 | 5 | 0 | 0 | 0 | 0 | 0 | 2 | 2 | 1 | 0 | 0 | 0 |
| 1500 | 4 | 0 | 0 | 0 | 0 | 0 | 2 | 1 | 1 | 0 | 0 | 0 |
| 1515 | 5 | 0 | 0 | 0 | 1 | 0 | 3 | 1 | 0 | 0 | 0 | 0 |
| 1530 | 3 | 0 | 0 | 0 | 0 | 0 | 2 | 1 | 0 | 0 | 0 | 0 |
| 1545 | 6 | 0 | 0 | 0 | 0 | 3 | 1 | 1 | 1 | 0 | 0 | 0 |
| 1600 | 10 | 0 | 0 | 0 | 0 | 0 | 1 | 4 | 4 | 1 | 0 | 0 |
| 1615 | 44 | 0 | 0 | 2 | 11 | 4 | 20 | 6 | 1 | 0 | 0 | 0 |
| 1630 | 31 | 0 | 0 | 0 | 0 | 4 | 15 | 9 | 3 | 0 | 0 | 0 |
| 1645 | 10 | 0 | 0 | 0 | 0 | 1 | 1 | 4 | 3 | 1 | 0 | 0 |
| 1700 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 1 | 1 | 0 | 0 |
| 1715 | 9 | 0 | 0 | 0 | 0 | 0 | 2 | 6 | 1 | 0 | 0 | 0 |
| 1730 | 11 | 0 | 0 | 0 | 0 | 1 | 8 | 2 | 0 | 0 | 0 | 0 |
| 1745 | 14 | 0 | 0 | 0 | 0 | 2 | 10 | 2 | 0 | 0 | 0 | 0 |
| 1800 | 5 | 0 | 0 | 0 | 0 | 1 | 0 | 3 | 1 | 0 | 0 | 0 |
| 1815 | 16 | 0 | 0 | 0 | 0 | 1 | 6 | 8 | 1 | 0 | 0 | 0 |
| 1830 | 14 | 0 | 0 | 0 | 0 | 0 | 6 | 7 | 1 | 0 | 0 | 0 |
| 1845 | 7 | 0 | 0 | 0 | 0 | 1 | 4 | 0 | 2 | 0 | 0 | 0 |
| 1900 | 3 | 0 | 0 | 0 | 0 | 1 | 1 | 1 | 0 | 0 | 0 | 0 |
| 1915 | 3 | 0 | 0 | 0 | 0 | 0 | 2 | 1 | 0 | 0 | 0 | 0 |
| 1930 | 1 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 |
| 1945 | 3 | 0 | 0 | 0 | 0 | 0 | 2 | 1 | 0 | 0 | 0 | 0 |
| 2000 | 8 | 0 | 0 | 0 | 0 | 0 | 6 | 2 | 0 | 0 | 0 | 0 |
| 2015 | 2 | 0 | 0 | 0 | 0 | 0 | 1 | 1 | 0 | 0 | 0 | 0 |
| 2030 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 |
| 2045 | 2 | 0 | 0 | 0 | 0 | 0 | 1 | 1 | 0 | 0 | 0 | 0 |
| 2100 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2115 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2130 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 |
| 2145 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2200 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 |
| 2215 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 |
| 2230 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2245 | 1 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 |
| 2300 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2315 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2330 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2345 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2400 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 08-09 | 76 | 0 | 0 | 0 | 0 | 2 | 15 | 41 | 17 | 1 | 0 | 0 |
| 17-18 | 39 | 0 | 0 | 0 | 0 | 4 | 20 | 13 | 2 | 0 | 0 | 0 |
| 07-19 | 412 | 0 | 0 | 2 | 16 | 38 | 151 | 149 | 51 | 5 | 0 | 0 |
| 07-23 | 436 | 0 | 0 | 2 | 16 | 38 | 165 | 156 | 54 | 5 | 0 | 0 |
| 00-24 | 441 | 0 | 0 | 2 | 16 | 39 | 167 | 156 | 56 | 5 | 0 | 0 |

Site Name - 24379-09
 Description - Cleveland Walk, East of Bathwick Hill
 Direction - West
 06 November 2024

| Time | Total | Vpp 85 | Mean | SD |
|------|-------|-----------|--------|-----|
| 0015 | 0 - | - | - | - |
| 0030 | 0 - | - | - | - |
| 0045 | 0 - | - | - | - |
| 0100 | 1 - | | 14 - | |
| 0115 | 1 - | | 18.3 - | |
| 0130 | 0 - | - | - | - |
| 0145 | 0 - | - | - | - |
| 0200 | 0 - | - | - | - |
| 0215 | 0 - | - | - | - |
| 0230 | 0 - | - | - | - |
| 0245 | 0 - | - | - | - |
| 0300 | 0 - | - | - | - |
| 0315 | 0 - | - | - | - |
| 0330 | 0 - | - | - | - |
| 0345 | 0 - | - | - | - |
| 0400 | 0 - | - | - | - |
| 0415 | 0 - | - | - | - |
| 0430 | 0 - | - | - | - |
| 0445 | 0 - | - | - | - |
| 0500 | 0 - | - | - | - |
| 0515 | 0 - | - | - | - |
| 0530 | 0 - | - | - | - |
| 0545 | 0 - | - | - | - |
| 0600 | 0 - | - | - | - |
| 0615 | 1 - | | 17.3 - | |
| 0630 | 0 - | - | - | - |
| 0645 | 1 - | | 25.5 - | |
| 0700 | 1 - | | 30 - | |
| 0715 | 4 - | | 18.1 | 3 |
| 0730 | 6 - | | 19.6 | 5.3 |
| 0745 | 1 - | | 19.7 - | |
| 0800 | 8 - | | 21.4 | 1.8 |
| 0815 | 23 | 26.6 | 23.5 | 2.9 |
| 0830 | 20 | 25.3 | 21.8 | 3.5 |
| 0845 | 23 | 26.7 | 22.8 | 3.3 |
| 0900 | 10 - | | 20 | 4.3 |
| 0915 | 3 - | | 24.6 | 3.5 |
| 0930 | 8 - | | 18.1 | 4.6 |
| 0945 | 2 - | | 17.4 | 0.5 |
| 1000 | 7 - | | 19.7 | 4 |
| 1015 | 12 | 22.9 | 19.3 | 4.8 |
| 1030 | 5 - | | 21.9 | 5.2 |
| 1045 | 6 - | | 20 | 2.8 |
| 1100 | 0 - | - | - | - |
| 1115 | 5 - | | 18.3 | 3.5 |
| 1130 | 5 - | | 17.3 | 4.8 |
| 1145 | 4 - | | 20.1 | 4.6 |
| 1200 | 7 - | | 19.5 | 4.3 |
| 1215 | 7 - | | 18.8 | 6.7 |
| 1230 | 3 - | | 12.7 | 2.5 |
| 1245 | 5 - | | 16.3 | 3.8 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
06 November 2024

| Time | Total | Vpp 85 | Mean | SD |
|--------------|------------|-------------|-------------|------------|
| 1300 | 2 - | | 19 | 2.2 |
| 1315 | 4 - | | 17.9 | 3.9 |
| 1330 | 8 - | | 19.3 | 7 |
| 1345 | 3 - | | 23.1 | 5 |
| 1400 | 8 - | | 19.2 | 6.3 |
| 1415 | 6 - | | 21.1 | 4.6 |
| 1430 | 7 - | | 20.9 | 5.5 |
| 1445 | 5 - | | 22.2 | 3.9 |
| 1500 | 4 - | | 21.4 | 5.5 |
| 1515 | 5 - | | 17.2 | 5.5 |
| 1530 | 3 - | | 20.4 | 2.4 |
| 1545 | 6 - | | 17.6 | 5.3 |
| 1600 | 10 - | | 25.2 | 3.7 |
| 1615 | 44 | 20.8 | 14.8 | 6.3 |
| 1630 | 31 | 22.9 | 18.7 | 3.8 |
| 1645 | 10 - | | 23 | 5 |
| 1700 | 3 - | | 27.8 | 3.1 |
| 1715 | 9 - | | 21.4 | 2.9 |
| 1730 | 11 | 21.6 | 19.2 | 2.8 |
| 1745 | 14 | 20.2 | 17.8 | 2.3 |
| 1800 | 5 - | | 22.3 | 4.8 |
| 1815 | 16 | 24.2 | 20.9 | 4.1 |
| 1830 | 14 | 23 | 20.6 | 2.7 |
| 1845 | 7 - | | 19.8 | 5.2 |
| 1900 | 3 - | | 17.2 | 6.2 |
| 1915 | 3 - | | 18.2 | 2.2 |
| 1930 | 1 - | | 18.7 - | |
| 1945 | 3 - | | 20.4 | 2.9 |
| 2000 | 8 - | | 19.1 | 2.6 |
| 2015 | 2 - | | 20.1 | 3.1 |
| 2030 | 1 - | | 28.3 - | |
| 2045 | 2 - | | 20.3 | 3.7 |
| 2100 | 0 - | | - | |
| 2115 | 0 - | | - | |
| 2130 | 1 - | | 21.1 - | |
| 2145 | 0 - | | - | |
| 2200 | 1 - | | 25.6 - | |
| 2215 | 1 - | | 27.8 - | |
| 2230 | 0 - | | - | |
| 2245 | 1 - | | 18.7 - | |
| 2300 | 0 - | | - | |
| 2315 | 0 - | | - | |
| 2330 | 0 - | | - | |
| 2345 | 0 - | | - | |
| 2400 | 0 - | | - | |
| 08-09 | 76 | 25.8 | 22.4 | 3.5 |
| 17-18 | 39 | 23.7 | 19.6 | 3.3 |
| 07-19 | 412 | 24.8 | 19.8 | 5 |
| 07-23 | 436 | 24.8 | 19.9 | 4.9 |
| 00-24 | 441 | 24.8 | 19.9 | 4.9 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
07 November 2024

| Time | Total | Cls 1 | Cls 2 | Cls 3 | Cls 4 | Cls 5 | Cls 6 | Cls 7 | Cls 8 | Cls 9 | Cls 10 | Cls 11 |
|------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|--------|--------|
| 0015 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0030 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0045 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0115 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0130 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0145 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0200 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0215 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0230 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0245 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0300 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0315 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0330 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0345 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0400 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0415 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0430 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0445 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0500 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0515 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0530 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0545 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0600 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0615 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0630 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0645 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0700 | 5 | 0 | 3 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0715 | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0730 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0745 | 3 | 0 | 2 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0800 | 9 | 0 | 8 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0815 | 18 | 0 | 15 | 0 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0830 | 32 | 0 | 31 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0845 | 14 | 0 | 14 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0900 | 13 | 1 | 12 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0915 | 5 | 0 | 2 | 0 | 1 | 2 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0930 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0945 | 9 | 0 | 6 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1000 | 10 | 0 | 5 | 0 | 3 | 2 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1015 | 4 | 0 | 2 | 0 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 |
| 1030 | 3 | 0 | 0 | 0 | 1 | 2 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1045 | 4 | 0 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1100 | 5 | 0 | 4 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1115 | 6 | 0 | 4 | 0 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1130 | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1145 | 6 | 0 | 3 | 0 | 2 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1200 | 3 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1215 | 6 | 0 | 6 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1230 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1245 | 4 | 0 | 3 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
07 November 2024

| Time | Total | Cls 1 | Cls 2 | Cls 3 | Cls 4 | Cls 5 | Cls 6 | Cls 7 | Cls 8 | Cls 9 | Cls 10 | Cls 11 |
|--------------|------------|----------|------------|----------|-----------|-----------|----------|----------|----------|----------|----------|----------|
| 1300 | 3 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1315 | 4 | 0 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1330 | 7 | 1 | 5 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1345 | 7 | 0 | 6 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1400 | 4 | 0 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1415 | 4 | 0 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1430 | 5 | 0 | 4 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1445 | 3 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1500 | 4 | 0 | 3 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1515 | 5 | 0 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1530 | 2 | 0 | 1 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1545 | 9 | 0 | 9 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1600 | 9 | 0 | 7 | 0 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1615 | 48 | 0 | 40 | 0 | 2 | 6 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1630 | 22 | 0 | 18 | 0 | 0 | 4 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1645 | 5 | 0 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1700 | 7 | 1 | 5 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1715 | 10 | 0 | 10 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1730 | 8 | 1 | 5 | 0 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1745 | 10 | 0 | 9 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1800 | 4 | 0 | 3 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1815 | 8 | 0 | 7 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1830 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1845 | 3 | 0 | 2 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1900 | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1915 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1930 | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1945 | 6 | 0 | 6 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2000 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2015 | 3 | 1 | 0 | 0 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2030 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2045 | 2 | 0 | 1 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2115 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2130 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2145 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2200 | 2 | 0 | 1 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2215 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2230 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2245 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2300 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2315 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2330 | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2345 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2400 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 08-09 | 77 | 1 | 72 | 0 | 0 | 4 | 0 | 0 | 0 | 0 | 0 | 0 |
| 17-18 | 32 | 1 | 27 | 0 | 0 | 4 | 0 | 0 | 0 | 0 | 0 | 0 |
| 07-19 | 354 | 4 | 295 | 0 | 15 | 39 | 1 | 0 | 0 | 0 | 0 | 0 |
| 07-23 | 373 | 5 | 309 | 0 | 15 | 43 | 1 | 0 | 0 | 0 | 0 | 0 |
| 00-24 | 383 | 5 | 317 | 0 | 17 | 43 | 1 | 0 | 0 | 0 | 0 | 0 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
07 November 2024

| Time | Total | Cls 12 | CI% 1 | CI% 2 | CI% 3 | CI% 4 | CI% 5 | CI% 6 | CI% 7 | CI% 8 | CI% 9 | CI% 10 |
|------|-------|--------|-------|-------|-------|-------|-------|-------|-------|-------|-------|--------|
| 0015 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0030 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0045 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0100 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0115 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0130 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0145 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0200 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0215 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0230 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0245 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0300 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0315 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0330 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0345 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0400 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0415 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0430 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0445 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0500 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0515 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0530 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0545 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0600 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0615 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0630 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0645 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0700 | 5 | 0 | 0 | 60 | 0 | 40 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0715 | 2 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0730 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 0745 | 3 | 0 | 0 | 66.67 | 0 | 0 | 33.33 | 0 | 0 | 0 | 0 | 0 |
| 0800 | 9 | 0 | 0 | 88.89 | 0 | 0 | 11.11 | 0 | 0 | 0 | 0 | 0 |
| 0815 | 18 | 0 | 0 | 83.33 | 0 | 0 | 16.67 | 0 | 0 | 0 | 0 | 0 |
| 0830 | 32 | 0 | 0 | 96.88 | 0 | 0 | 3.125 | 0 | 0 | 0 | 0 | 0 |
| 0845 | 14 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0900 | 13 | 0 | 7.692 | 92.31 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0915 | 5 | 0 | 0 | 40 | 0 | 20 | 40 | 0 | 0 | 0 | 0 | 0 |
| 0930 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0945 | 9 | 0 | 0 | 66.67 | 0 | 33.33 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1000 | 10 | 0 | 0 | 50 | 0 | 30 | 20 | 0 | 0 | 0 | 0 | 0 |
| 1015 | 4 | 0 | 0 | 50 | 0 | 25 | 0 | 25 | 0 | 0 | 0 | 0 |
| 1030 | 3 | 0 | 0 | 0 | 0 | 33.33 | 66.67 | 0 | 0 | 0 | 0 | 0 |
| 1045 | 4 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1100 | 5 | 0 | 0 | 80 | 0 | 0 | 20 | 0 | 0 | 0 | 0 | 0 |
| 1115 | 6 | 0 | 0 | 66.67 | 0 | 0 | 33.33 | 0 | 0 | 0 | 0 | 0 |
| 1130 | 2 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1145 | 6 | 0 | 0 | 50 | 0 | 33.33 | 16.67 | 0 | 0 | 0 | 0 | 0 |
| 1200 | 3 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1215 | 6 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1230 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1245 | 4 | 0 | 0 | 75 | 0 | 0 | 25 | 0 | 0 | 0 | 0 | 0 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
07 November 2024

| Time | Total | Cls 12 | CI% 1 | CI% 2 | CI% 3 | CI% 4 | CI% 5 | CI% 6 | CI% 7 | CI% 8 | CI% 9 | CI% 10 |
|--------------|------------|-----------|--------------|--------------|----------|--------------|--------------|--------------|----------|----------|----------|-----------|
| 1300 | 3 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1315 | 4 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1330 | 7 | 0 | 14.29 | 71.43 | 0 | 14.29 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1345 | 7 | 0 | 0 | 85.71 | 0 | 0 | 14.29 | 0 | 0 | 0 | 0 | 0 |
| 1400 | 4 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1415 | 4 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1430 | 5 | 0 | 0 | 80 | 0 | 0 | 20 | 0 | 0 | 0 | 0 | 0 |
| 1445 | 3 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1500 | 4 | 0 | 0 | 75 | 0 | 0 | 25 | 0 | 0 | 0 | 0 | 0 |
| 1515 | 5 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1530 | 2 | 0 | 0 | 50 | 0 | 0 | 50 | 0 | 0 | 0 | 0 | 0 |
| 1545 | 9 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1600 | 9 | 0 | 0 | 77.78 | 0 | 0 | 22.22 | 0 | 0 | 0 | 0 | 0 |
| 1615 | 48 | 0 | 0 | 83.33 | 0 | 4.167 | 12.5 | 0 | 0 | 0 | 0 | 0 |
| 1630 | 22 | 0 | 0 | 81.82 | 0 | 0 | 18.18 | 0 | 0 | 0 | 0 | 0 |
| 1645 | 5 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1700 | 7 | 0 | 14.29 | 71.43 | 0 | 14.29 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1715 | 10 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1730 | 8 | 0 | 12.5 | 62.5 | 0 | 0 | 25 | 0 | 0 | 0 | 0 | 0 |
| 1745 | 10 | 0 | 0 | 90 | 0 | 0 | 10 | 0 | 0 | 0 | 0 | 0 |
| 1800 | 4 | 0 | 0 | 75 | 0 | 0 | 25 | 0 | 0 | 0 | 0 | 0 |
| 1815 | 8 | 0 | 0 | 87.5 | 0 | 0 | 12.5 | 0 | 0 | 0 | 0 | 0 |
| 1830 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1845 | 3 | 0 | 0 | 66.67 | 0 | 0 | 33.33 | 0 | 0 | 0 | 0 | 0 |
| 1900 | 2 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1915 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1930 | 2 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1945 | 6 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2000 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2015 | 3 | 0 | 33.33 | 0 | 0 | 0 | 66.67 | 0 | 0 | 0 | 0 | 0 |
| 2030 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2045 | 2 | 0 | 0 | 50 | 0 | 0 | 50 | 0 | 0 | 0 | 0 | 0 |
| 2100 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2115 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2130 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2145 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2200 | 2 | 0 | 0 | 50 | 0 | 0 | 50 | 0 | 0 | 0 | 0 | 0 |
| 2215 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2230 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2245 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2300 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2315 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2330 | 2 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2345 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2400 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 08-09 | 77 | 0 | 1.299 | 93.51 | 0 | 0 | 5.195 | 0 | 0 | 0 | 0 | 0 |
| 17-18 | 32 | 0 | 3.125 | 84.38 | 0 | 0 | 12.5 | 0 | 0 | 0 | 0 | 0 |
| 07-19 | 354 | 0 | 1.13 | 83.33 | 0 | 4.237 | 11.02 | 0.282 | 0 | 0 | 0 | 0 |
| 07-23 | 373 | 0 | 1.34 | 82.84 | 0 | 4.021 | 11.53 | 0.268 | 0 | 0 | 0 | 0 |
| 00-24 | 383 | 0 | 1.305 | 82.77 | 0 | 4.439 | 11.23 | 0.261 | 0 | 0 | 0 | 0 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
07 November 2024

| Time | Total | CI% 11 | CI% 12 | Vbin 0 5 | Vbin 5 10 | Vbin 10 15 | Vbin 15 20 | Vbin 20 25 | Vbin 25 30 | Vbin 30 35 | Vbin 35 40 | Vbin 40 45 |
|------|-------|-----------|-----------|----------------|-----------------|------------------|------------------|------------------|------------------|------------------|------------------|------------------|
| 0015 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0030 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0045 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0100 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0115 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0130 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0145 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0200 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0215 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0230 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0245 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0300 | 1 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 |
| 0315 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0330 | 1 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 |
| 0345 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0400 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0415 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0430 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0445 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0500 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0515 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0530 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0545 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0600 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0615 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0630 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0645 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0700 | 5 | 0 | 0 | 0 | 0 | 0 | 2 | 0 | 3 | 0 | 0 | 0 |
| 0715 | 2 | 0 | 0 | 0 | 0 | 0 | 2 | 0 | 0 | 0 | 0 | 0 |
| 0730 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0745 | 3 | 0 | 0 | 0 | 0 | 1 | 0 | 1 | 1 | 0 | 0 | 0 |
| 0800 | 9 | 0 | 0 | 0 | 0 | 0 | 0 | 8 | 1 | 0 | 0 | 0 |
| 0815 | 18 | 0 | 0 | 0 | 0 | 0 | 8 | 9 | 1 | 0 | 0 | 0 |
| 0830 | 32 | 0 | 0 | 0 | 0 | 1 | 7 | 18 | 6 | 0 | 0 | 0 |
| 0845 | 14 | 0 | 0 | 0 | 0 | 1 | 6 | 6 | 1 | 0 | 0 | 0 |
| 0900 | 13 | 0 | 0 | 0 | 0 | 1 | 4 | 5 | 3 | 0 | 0 | 0 |
| 0915 | 5 | 0 | 0 | 0 | 0 | 0 | 1 | 4 | 0 | 0 | 0 | 0 |
| 0930 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 |
| 0945 | 9 | 0 | 0 | 0 | 0 | 1 | 2 | 4 | 2 | 0 | 0 | 0 |
| 1000 | 10 | 0 | 0 | 0 | 1 | 0 | 2 | 5 | 2 | 0 | 0 | 0 |
| 1015 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 2 | 2 | 0 | 0 | 0 |
| 1030 | 3 | 0 | 0 | 0 | 0 | 0 | 1 | 2 | 0 | 0 | 0 | 0 |
| 1045 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 4 | 0 | 0 | 0 | 0 |
| 1100 | 5 | 0 | 0 | 0 | 0 | 3 | 1 | 1 | 0 | 0 | 0 | 0 |
| 1115 | 6 | 0 | 0 | 0 | 1 | 0 | 2 | 3 | 0 | 0 | 0 | 0 |
| 1130 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 2 | 0 | 0 | 0 | 0 |
| 1145 | 6 | 0 | 0 | 1 | 0 | 0 | 1 | 4 | 0 | 0 | 0 | 0 |
| 1200 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 2 | 0 | 0 | 0 |
| 1215 | 6 | 0 | 0 | 0 | 0 | 0 | 3 | 2 | 1 | 0 | 0 | 0 |
| 1230 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 |
| 1245 | 4 | 0 | 0 | 0 | 0 | 0 | 2 | 0 | 1 | 0 | 1 | 0 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
07 November 2024

| Time | Total | CI% 11 | CI% 12 | Vbin 0 5 | Vbin 5 10 | Vbin 10 15 | Vbin 15 20 | Vbin 20 25 | Vbin 25 30 | Vbin 30 35 | Vbin 35 40 | Vbin 40 45 |
|--------------|------------|-----------|-----------|----------------|-----------------|------------------|------------------|------------------|------------------|------------------|------------------|------------------|
| 1300 | 3 | 0 | 0 | 0 | 0 | 0 | 1 | 2 | 0 | 0 | 0 | 0 |
| 1315 | 4 | 0 | 0 | 0 | 0 | 0 | 1 | 2 | 1 | 0 | 0 | 0 |
| 1330 | 7 | 0 | 0 | 0 | 0 | 1 | 1 | 5 | 0 | 0 | 0 | 0 |
| 1345 | 7 | 0 | 0 | 0 | 1 | 0 | 1 | 4 | 0 | 1 | 0 | 0 |
| 1400 | 4 | 0 | 0 | 0 | 0 | 0 | 1 | 2 | 1 | 0 | 0 | 0 |
| 1415 | 4 | 0 | 0 | 0 | 0 | 0 | 4 | 0 | 0 | 0 | 0 | 0 |
| 1430 | 5 | 0 | 0 | 0 | 0 | 2 | 2 | 1 | 0 | 0 | 0 | 0 |
| 1445 | 3 | 0 | 0 | 0 | 0 | 1 | 0 | 2 | 0 | 0 | 0 | 0 |
| 1500 | 4 | 0 | 0 | 0 | 0 | 0 | 1 | 2 | 1 | 0 | 0 | 0 |
| 1515 | 5 | 0 | 0 | 0 | 0 | 1 | 0 | 1 | 3 | 0 | 0 | 0 |
| 1530 | 2 | 0 | 0 | 0 | 0 | 0 | 1 | 1 | 0 | 0 | 0 | 0 |
| 1545 | 9 | 0 | 0 | 0 | 0 | 0 | 3 | 5 | 1 | 0 | 0 | 0 |
| 1600 | 9 | 0 | 0 | 0 | 0 | 0 | 2 | 5 | 2 | 0 | 0 | 0 |
| 1615 | 48 | 0 | 0 | 0 | 0 | 7 | 26 | 14 | 1 | 0 | 0 | 0 |
| 1630 | 22 | 0 | 0 | 0 | 1 | 1 | 8 | 9 | 2 | 1 | 0 | 0 |
| 1645 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 2 | 3 | 0 | 0 | 0 |
| 1700 | 7 | 0 | 0 | 0 | 0 | 0 | 3 | 2 | 2 | 0 | 0 | 0 |
| 1715 | 10 | 0 | 0 | 0 | 0 | 0 | 1 | 5 | 4 | 0 | 0 | 0 |
| 1730 | 8 | 0 | 0 | 0 | 0 | 1 | 2 | 1 | 4 | 0 | 0 | 0 |
| 1745 | 10 | 0 | 0 | 0 | 0 | 0 | 5 | 4 | 1 | 0 | 0 | 0 |
| 1800 | 4 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 3 | 0 | 0 | 0 |
| 1815 | 8 | 0 | 0 | 0 | 0 | 2 | 1 | 3 | 2 | 0 | 0 | 0 |
| 1830 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 |
| 1845 | 3 | 0 | 0 | 0 | 0 | 0 | 1 | 1 | 1 | 0 | 0 | 0 |
| 1900 | 2 | 0 | 0 | 0 | 0 | 0 | 2 | 0 | 0 | 0 | 0 | 0 |
| 1915 | 1 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1930 | 2 | 0 | 0 | 0 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1945 | 6 | 0 | 0 | 0 | 0 | 2 | 0 | 0 | 4 | 0 | 0 | 0 |
| 2000 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2015 | 3 | 0 | 0 | 0 | 0 | 0 | 1 | 2 | 0 | 0 | 0 | 0 |
| 2030 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2045 | 2 | 0 | 0 | 0 | 0 | 0 | 1 | 1 | 0 | 0 | 0 | 0 |
| 2100 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2115 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2130 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2145 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2200 | 2 | 0 | 0 | 0 | 0 | 0 | 1 | 1 | 0 | 0 | 0 | 0 |
| 2215 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2230 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 |
| 2245 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 |
| 2300 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 |
| 2315 | 1 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2330 | 2 | 0 | 0 | 0 | 0 | 0 | 2 | 0 | 0 | 0 | 0 | 0 |
| 2345 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2400 | 0 - | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 08-09 | 77 | 0 | 0 | 0 | 0 | 3 | 25 | 38 | 11 | 0 | 0 | 0 |
| 17-18 | 32 | 0 | 0 | 0 | 0 | 1 | 9 | 10 | 12 | 0 | 0 | 0 |
| 07-19 | 354 | 0 | 0 | 1 | 4 | 24 | 110 | 156 | 56 | 2 | 1 | 0 |
| 07-23 | 373 | 0 | 0 | 2 | 4 | 28 | 113 | 163 | 60 | 2 | 1 | 0 |
| 00-24 | 383 | 0 | 0 | 2 | 4 | 29 | 119 | 163 | 63 | 2 | 1 | 0 |

Site Name - 24379-09
 Description - Cleveland Walk, East of Bathwick Hill
 Direction - West
 07 November 2024

| Time | Total | Vpp 85 | Mean | SD |
|------|-------|-----------|--------|-----|
| 0015 | 0 - | - | - | - |
| 0030 | 0 - | - | - | - |
| 0045 | 0 - | - | - | - |
| 0100 | 0 - | - | - | - |
| 0115 | 0 - | - | - | - |
| 0130 | 0 - | - | - | - |
| 0145 | 0 - | - | - | - |
| 0200 | 0 - | - | - | - |
| 0215 | 0 - | - | - | - |
| 0230 | 0 - | - | - | - |
| 0245 | 0 - | - | - | - |
| 0300 | 1 - | - | 19.2 - | - |
| 0315 | 0 - | - | - | - |
| 0330 | 1 - | - | 15.8 - | - |
| 0345 | 0 - | - | - | - |
| 0400 | 0 - | - | - | - |
| 0415 | 0 - | - | - | - |
| 0430 | 0 - | - | - | - |
| 0445 | 0 - | - | - | - |
| 0500 | 0 - | - | - | - |
| 0515 | 0 - | - | - | - |
| 0530 | 0 - | - | - | - |
| 0545 | 0 - | - | - | - |
| 0600 | 0 - | - | - | - |
| 0615 | 0 - | - | - | - |
| 0630 | 0 - | - | - | - |
| 0645 | 0 - | - | - | - |
| 0700 | 5 - | - | 23.5 | 7.1 |
| 0715 | 2 - | - | 18.9 | 0.4 |
| 0730 | 0 - | - | - | - |
| 0745 | 3 - | - | 20.1 | 8.3 |
| 0800 | 9 - | - | 22.5 | 1.9 |
| 0815 | 18 | 24 | 20.7 | 2.5 |
| 0830 | 32 | 25.8 | 21.9 | 3.6 |
| 0845 | 14 | 23 | 19.6 | 3.5 |
| 0900 | 13 | 26.9 | 21.1 | 4.8 |
| 0915 | 5 - | - | 21.1 | 2.6 |
| 0930 | 1 - | - | 29.7 - | - |
| 0945 | 9 - | - | 21.2 | 5.3 |
| 1000 | 10 - | - | 21.9 | 6 |
| 1015 | 4 - | - | 24.5 | 2.5 |
| 1030 | 3 - | - | 21.6 | 2.5 |
| 1045 | 4 - | - | 22.4 | 1.1 |
| 1100 | 5 - | - | 15.9 | 3.5 |
| 1115 | 6 - | - | 19.7 | 5.8 |
| 1130 | 2 - | - | 22.3 | 0.8 |
| 1145 | 6 - | - | 17.5 | 7.7 |
| 1200 | 3 - | - | 24.4 | 2 |
| 1215 | 6 - | - | 20.7 | 3.6 |
| 1230 | 1 - | - | 20.3 - | - |
| 1245 | 4 - | - | 25.6 | 8.7 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
07 November 2024

| Time | Total | Vpp 85 | Mean | SD |
|--------------|------------|-------------|-------------|------------|
| 1300 | 3 - | | 21.4 | 3.3 |
| 1315 | 4 - | | 23.5 | 3.1 |
| 1330 | 7 - | | 20.7 | 3.6 |
| 1345 | 7 - | | 21.2 | 6.7 |
| 1400 | 4 - | | 21.9 | 4.7 |
| 1415 | 4 - | | 17.9 | 1 |
| 1430 | 5 - | | 17 | 3.9 |
| 1445 | 3 - | | 19.5 | 5.3 |
| 1500 | 4 - | | 22.4 | 3 |
| 1515 | 5 - | | 22.4 | 6.9 |
| 1530 | 2 - | | 19.3 | 2.6 |
| 1545 | 9 - | | 20.7 | 3 |
| 1600 | 9 - | | 22.3 | 3.3 |
| 1615 | 48 | 22.2 | 18.4 | 3.3 |
| 1630 | 22 | 24.6 | 20.7 | 4.9 |
| 1645 | 5 - | | 25.5 | 2.6 |
| 1700 | 7 - | | 21.3 | 4.3 |
| 1715 | 10 - | | 24.4 | 3 |
| 1730 | 8 - | | 22.2 | 5.5 |
| 1745 | 10 - | | 20.6 | 2.6 |
| 1800 | 4 - | | 24.8 | 3.9 |
| 1815 | 8 - | | 21.1 | 4.7 |
| 1830 | 1 - | | 20.7 - | |
| 1845 | 3 - | | 21.5 | 5 |
| 1900 | 2 - | | 19.1 | 0.9 |
| 1915 | 1 - | | 3.4 - | |
| 1930 | 2 - | | 11.7 | 0 |
| 1945 | 6 - | | 21.7 | 7.8 |
| 2000 | 0 - | | - | |
| 2015 | 3 - | | 21.8 | 3.5 |
| 2030 | 0 - | | - | |
| 2045 | 2 - | | 18.9 | 2 |
| 2100 | 0 - | | - | |
| 2115 | 0 - | | - | |
| 2130 | 0 - | | - | |
| 2145 | 0 - | | - | |
| 2200 | 2 - | | 20.9 | 4.9 |
| 2215 | 0 - | | - | |
| 2230 | 1 - | | 22.5 - | |
| 2245 | 1 - | | 22 - | |
| 2300 | 1 - | | 21.8 - | |
| 2315 | 1 - | | 13.7 - | |
| 2330 | 2 - | | 17.7 | 0 |
| 2345 | 0 - | | - | |
| 2400 | 0 - | | - | |
| 08-09 | 77 | 24.8 | 21.1 | 3.6 |
| 17-18 | 32 | 27.2 | 22.7 | 4 |
| 07-19 | 354 | 25.3 | 20.9 | 4.3 |
| 07-23 | 373 | 25.4 | 20.8 | 4.5 |
| 00-24 | 383 | 25.4 | 20.8 | 4.5 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
08 November 2024

| Time | Total | Cls 1 | Cls 2 | Cls 3 | Cls 4 | Cls 5 | Cls 6 | Cls 7 | Cls 8 | Cls 9 | Cls 10 | Cls 11 |
|--------------|------------|----------|------------|----------|-----------|-----------|----------|----------|----------|----------|----------|----------|
| 1300 | 4 | 0 | 3 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1315 | 5 | 0 | 3 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1330 | 3 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1345 | 2 | 0 | 0 | 0 | 1 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1400 | 6 | 0 | 6 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1415 | 7 | 0 | 6 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1430 | 4 | 0 | 2 | 0 | 1 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1445 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1500 | 5 | 1 | 2 | 0 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 |
| 1515 | 8 | 0 | 6 | 0 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1530 | 4 | 0 | 3 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1545 | 7 | 1 | 5 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1600 | 6 | 0 | 5 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1615 | 34 | 0 | 31 | 0 | 1 | 1 | 1 | 0 | 0 | 0 | 0 | 0 |
| 1630 | 26 | 1 | 22 | 0 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1645 | 10 | 0 | 10 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1700 | 11 | 2 | 7 | 0 | 1 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1715 | 11 | 0 | 9 | 0 | 1 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1730 | 5 | 0 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1745 | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1800 | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1815 | 6 | 0 | 5 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1830 | 7 | 0 | 6 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 |
| 1845 | 3 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1900 | 3 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1915 | 6 | 0 | 6 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1930 | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1945 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2000 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2015 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2030 | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2045 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2115 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2130 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2145 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2200 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2215 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2230 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2245 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2300 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2315 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2330 | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2345 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2400 | 1 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 |
| 08-09 | 75 | 1 | 62 | 0 | 2 | 8 | 2 | 0 | 0 | 0 | 0 | 0 |
| 17-18 | 20 | 0 | 18 | 0 | 1 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 07-19 | 332 | 7 | 269 | 0 | 18 | 32 | 6 | 0 | 0 | 0 | 0 | 0 |
| 07-23 | 346 | 7 | 283 | 0 | 18 | 32 | 6 | 0 | 0 | 0 | 0 | 0 |
| 00-24 | 353 | 8 | 288 | 0 | 18 | 32 | 7 | 0 | 0 | 0 | 0 | 0 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
08 November 2024

| Time | Total | Cls 12 | CI% 1 | CI% 2 | CI% 3 | CI% 4 | CI% 5 | CI% 6 | CI% 7 | CI% 8 | CI% 9 | CI% 10 |
|--------------|------------|----------|--------------|--------------|----------|--------------|--------------|--------------|----------|----------|----------|----------|
| 1300 | 4 | 0 | 0 | 75 | 0 | 25 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1315 | 5 | 0 | 0 | 60 | 0 | 40 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1330 | 3 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1345 | 2 | 0 | 0 | 0 | 0 | 50 | 50 | 0 | 0 | 0 | 0 | 0 |
| 1400 | 6 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1415 | 7 | 0 | 0 | 85.71 | 0 | 14.29 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1430 | 4 | 0 | 0 | 50 | 0 | 25 | 25 | 0 | 0 | 0 | 0 | 0 |
| 1445 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 1500 | 5 | 0 | 20 | 40 | 0 | 20 | 0 | 20 | 0 | 0 | 0 | 0 |
| 1515 | 8 | 0 | 0 | 75 | 0 | 0 | 25 | 0 | 0 | 0 | 0 | 0 |
| 1530 | 4 | 0 | 0 | 75 | 0 | 0 | 25 | 0 | 0 | 0 | 0 | 0 |
| 1545 | 7 | 0 | 14.29 | 71.43 | 0 | 0 | 14.29 | 0 | 0 | 0 | 0 | 0 |
| 1600 | 6 | 0 | 0 | 83.33 | 0 | 0 | 16.67 | 0 | 0 | 0 | 0 | 0 |
| 1615 | 34 | 0 | 0 | 91.18 | 0 | 2.941 | 2.941 | 2.941 | 0 | 0 | 0 | 0 |
| 1630 | 26 | 0 | 3.846 | 84.62 | 0 | 0 | 11.54 | 0 | 0 | 0 | 0 | 0 |
| 1645 | 10 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1700 | 11 | 0 | 18.18 | 63.64 | 0 | 9.091 | 9.091 | 0 | 0 | 0 | 0 | 0 |
| 1715 | 11 | 0 | 0 | 81.82 | 0 | 9.091 | 9.091 | 0 | 0 | 0 | 0 | 0 |
| 1730 | 5 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1745 | 2 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1800 | 2 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1815 | 6 | 0 | 0 | 83.33 | 0 | 0 | 16.67 | 0 | 0 | 0 | 0 | 0 |
| 1830 | 7 | 0 | 0 | 85.71 | 0 | 0 | 0 | 14.29 | 0 | 0 | 0 | 0 |
| 1845 | 3 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1900 | 3 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1915 | 6 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1930 | 2 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1945 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2000 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2015 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2030 | 2 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2045 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2100 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2115 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2130 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2145 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2200 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2215 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2230 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2245 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2300 | 1 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2315 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2330 | 2 | 0 | 0 | 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2345 | 0 | 0 | - | - | - | - | - | - | - | - | - | - |
| 2400 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 100 | 0 | 0 | 0 | 0 |
| 08-09 | 75 | 0 | 1.333 | 82.67 | 0 | 2.667 | 10.67 | 2.667 | 0 | 0 | 0 | 0 |
| 17-18 | 20 | 0 | 0 | 90 | 0 | 5 | 5 | 0 | 0 | 0 | 0 | 0 |
| 07-19 | 332 | 0 | 2.108 | 81.02 | 0 | 5.422 | 9.639 | 1.807 | 0 | 0 | 0 | 0 |
| 07-23 | 346 | 0 | 2.023 | 81.79 | 0 | 5.202 | 9.249 | 1.734 | 0 | 0 | 0 | 0 |
| 00-24 | 353 | 0 | 2.266 | 81.59 | 0 | 5.099 | 9.065 | 1.983 | 0 | 0 | 0 | 0 |

Site Name - 24379-09
 Description - Cleveland Walk, East of Bathwick Hill
 Direction - West
 08 November 2024

| Time | Total | CI% 11 | CI% 12 | Vbin 0 5 | Vbin 5 10 | Vbin 10 15 | Vbin 15 20 | Vbin 20 25 | Vbin 25 30 | Vbin 30 35 | Vbin 35 40 | Vbin 40 45 |
|------|-------|-----------|-----------|----------------|-----------------|------------------|------------------|------------------|------------------|------------------|------------------|------------------|
| 0015 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0030 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0045 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0100 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0115 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0130 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0145 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0200 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0215 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0230 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0245 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0300 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0315 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0330 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0345 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0400 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0415 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0430 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0445 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0500 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0515 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0530 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0545 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0600 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0615 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0630 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0645 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0700 | 4 | 0 | 0 | 0 | 0 | 0 | 2 | 1 | 0 | 1 | 0 | 0 |
| 0715 | 0 | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0730 | 2 | 0 | 0 | 0 | 0 | 1 | 0 | 1 | 0 | 0 | 0 | 0 |
| 0745 | 1 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0800 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 3 | 1 | 0 | 0 | 0 |
| 0815 | 16 | 0 | 0 | 0 | 0 | 0 | 1 | 10 | 5 | 0 | 0 | 0 |
| 0830 | 23 | 0 | 0 | 0 | 1 | 0 | 6 | 12 | 2 | 2 | 0 | 0 |
| 0845 | 22 | 0 | 0 | 0 | 1 | 1 | 8 | 8 | 1 | 2 | 1 | 0 |
| 0900 | 14 | 0 | 0 | 1 | 0 | 0 | 6 | 5 | 2 | 0 | 0 | 0 |
| 0915 | 8 | 0 | 0 | 0 | 0 | 0 | 5 | 2 | 1 | 0 | 0 | 0 |
| 0930 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 |
| 0945 | 4 | 0 | 0 | 0 | 0 | 2 | 1 | 1 | 0 | 0 | 0 | 0 |
| 1000 | 1 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 |
| 1015 | 5 | 0 | 0 | 0 | 0 | 1 | 2 | 2 | 0 | 0 | 0 | 0 |
| 1030 | 1 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 |
| 1045 | 4 | 0 | 0 | 0 | 0 | 0 | 2 | 1 | 1 | 0 | 0 | 0 |
| 1100 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 3 | 0 | 1 | 0 | 0 |
| 1115 | 7 | 0 | 0 | 0 | 1 | 1 | 2 | 2 | 1 | 0 | 0 | 0 |
| 1130 | 3 | 0 | 0 | 0 | 0 | 1 | 1 | 0 | 1 | 0 | 0 | 0 |
| 1145 | 3 | 0 | 0 | 0 | 0 | 1 | 0 | 2 | 0 | 0 | 0 | 0 |
| 1200 | 8 | 0 | 0 | 0 | 0 | 1 | 3 | 3 | 1 | 0 | 0 | 0 |
| 1215 | 10 | 0 | 0 | 0 | 0 | 0 | 5 | 5 | 0 | 0 | 0 | 0 |
| 1230 | 4 | 0 | 0 | 0 | 0 | 1 | 3 | 0 | 0 | 0 | 0 | 0 |
| 1245 | 6 | 0 | 0 | 0 | 0 | 2 | 2 | 1 | 0 | 1 | 0 | 0 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
08 November 2024

| Time | Total | CI% 11 | CI% 12 | Vbin 0 5 | Vbin 5 10 | Vbin 10 15 | Vbin 15 20 | Vbin 20 25 | Vbin 25 30 | Vbin 30 35 | Vbin 35 40 | Vbin 40 45 |
|--------------|------------|-----------|-----------|----------------|-----------------|------------------|------------------|------------------|------------------|------------------|------------------|------------------|
| 1300 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 2 | 0 | 1 | 0 |
| 1315 | 5 | 0 | 0 | 0 | 0 | 1 | 3 | 1 | 0 | 0 | 0 | 0 |
| 1330 | 3 | 0 | 0 | 0 | 0 | 0 | 1 | 1 | 1 | 0 | 0 | 0 |
| 1345 | 2 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 1 | 0 | 0 | 0 |
| 1400 | 6 | 0 | 0 | 0 | 0 | 0 | 0 | 4 | 2 | 0 | 0 | 0 |
| 1415 | 7 | 0 | 0 | 0 | 0 | 1 | 4 | 1 | 1 | 0 | 0 | 0 |
| 1430 | 4 | 0 | 0 | 0 | 0 | 0 | 2 | 1 | 1 | 0 | 0 | 0 |
| 1445 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 1500 | 5 | 0 | 0 | 0 | 1 | 1 | 1 | 2 | 0 | 0 | 0 | 0 |
| 1515 | 8 | 0 | 0 | 0 | 0 | 1 | 2 | 5 | 0 | 0 | 0 | 0 |
| 1530 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 2 | 2 | 0 | 0 | 0 |
| 1545 | 7 | 0 | 0 | 0 | 0 | 0 | 3 | 3 | 1 | 0 | 0 | 0 |
| 1600 | 6 | 0 | 0 | 0 | 0 | 0 | 0 | 5 | 1 | 0 | 0 | 0 |
| 1615 | 34 | 0 | 0 | 0 | 0 | 8 | 21 | 3 | 2 | 0 | 0 | 0 |
| 1630 | 26 | 0 | 0 | 0 | 0 | 2 | 18 | 5 | 1 | 0 | 0 | 0 |
| 1645 | 10 | 0 | 0 | 0 | 0 | 1 | 2 | 6 | 1 | 0 | 0 | 0 |
| 1700 | 11 | 0 | 0 | 0 | 2 | 2 | 2 | 3 | 1 | 1 | 0 | 0 |
| 1715 | 11 | 0 | 0 | 0 | 2 | 0 | 3 | 5 | 1 | 0 | 0 | 0 |
| 1730 | 5 | 0 | 0 | 0 | 0 | 0 | 1 | 1 | 2 | 1 | 0 | 0 |
| 1745 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 2 | 0 | 0 | 0 |
| 1800 | 2 | 0 | 0 | 0 | 0 | 0 | 1 | 1 | 0 | 0 | 0 | 0 |
| 1815 | 6 | 0 | 0 | 0 | 0 | 1 | 2 | 3 | 0 | 0 | 0 | 0 |
| 1830 | 7 | 0 | 0 | 0 | 0 | 0 | 3 | 1 | 2 | 1 | 0 | 0 |
| 1845 | 3 | 0 | 0 | 0 | 0 | 1 | 1 | 1 | 0 | 0 | 0 | 0 |
| 1900 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 3 | 0 | 0 | 0 |
| 1915 | 6 | 0 | 0 | 0 | 0 | 0 | 2 | 2 | 1 | 1 | 0 | 0 |
| 1930 | 2 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 1 | 0 | 0 | 0 |
| 1945 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2000 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2015 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 |
| 2030 | 2 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 1 | 0 | 0 | 0 |
| 2045 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2100 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2115 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 |
| 2130 | 1 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 |
| 2145 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2200 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2215 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2230 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2245 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2300 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 |
| 2315 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2330 | 2 | 0 | 0 | 0 | 0 | 0 | 2 | 0 | 0 | 0 | 0 | 0 |
| 2345 | 0 - | - | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2400 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 |
| 08-09 | 75 | 0 | 0 | 1 | 2 | 1 | 21 | 35 | 10 | 4 | 1 | 0 |
| 17-18 | 20 | 0 | 0 | 0 | 2 | 0 | 5 | 7 | 5 | 1 | 0 | 0 |
| 07-19 | 332 | 0 | 0 | 1 | 8 | 33 | 119 | 117 | 43 | 9 | 2 | 0 |
| 07-23 | 346 | 0 | 0 | 1 | 8 | 33 | 124 | 120 | 47 | 11 | 2 | 0 |
| 00-24 | 353 | 0 | 0 | 1 | 8 | 33 | 128 | 122 | 47 | 12 | 2 | 0 |

Site Name - 24379-09
 Description - Cleveland Walk, East of Bathwick Hill
 Direction - West
 08 November 2024

| Time | Total | Vpp 85 | Mean | SD |
|------|-------|-----------|--------|-----|
| 0015 | 0 - | - | - | - |
| 0030 | 0 - | - | - | - |
| 0045 | 0 - | - | - | - |
| 0100 | 0 - | - | - | - |
| 0115 | 0 - | - | - | - |
| 0130 | 0 - | - | - | - |
| 0145 | 0 - | - | - | - |
| 0200 | 0 - | - | - | - |
| 0215 | 0 - | - | - | - |
| 0230 | 0 - | - | - | - |
| 0245 | 0 - | - | - | - |
| 0300 | 0 - | - | - | - |
| 0315 | 0 - | - | - | - |
| 0330 | 0 - | - | - | - |
| 0345 | 0 - | - | - | - |
| 0400 | 0 - | - | - | - |
| 0415 | 0 - | - | - | - |
| 0430 | 0 - | - | - | - |
| 0445 | 0 - | - | - | - |
| 0500 | 0 - | - | - | - |
| 0515 | 0 - | - | - | - |
| 0530 | 0 - | - | - | - |
| 0545 | 0 - | - | - | - |
| 0600 | 0 - | - | - | - |
| 0615 | 0 - | - | - | - |
| 0630 | 0 - | - | - | - |
| 0645 | 0 - | - | - | - |
| 0700 | 4 - | | 21.6 | 6.5 |
| 0715 | 0 - | - | - | - |
| 0730 | 2 - | | 18.6 | 5.8 |
| 0745 | 1 - | | 10.2 - | - |
| 0800 | 4 - | | 24.4 | 2.6 |
| 0815 | 16 | 27.8 | 23.4 | 3.1 |
| 0830 | 23 | 26.9 | 21.4 | 4.8 |
| 0845 | 22 | 29.2 | 21.1 | 6.5 |
| 0900 | 14 | 25.7 | 19.8 | 6.2 |
| 0915 | 8 - | | 20.7 | 3.5 |
| 0930 | 1 - | | 22.7 - | - |
| 0945 | 4 - | | 16.2 | 5.4 |
| 1000 | 1 - | | 17.7 - | - |
| 1015 | 5 - | | 18 | 4.1 |
| 1030 | 1 - | | 17.4 - | - |
| 1045 | 4 - | | 21.3 | 3.6 |
| 1100 | 4 - | | 24.9 | 3.7 |
| 1115 | 7 - | | 18.5 | 7.4 |
| 1130 | 3 - | | 19.9 | 7.3 |
| 1145 | 3 - | | 19.7 | 4.7 |
| 1200 | 8 - | | 19.9 | 5.5 |
| 1215 | 10 - | | 19.2 | 2.2 |
| 1230 | 4 - | | 16.4 | 2.2 |
| 1245 | 6 - | | 19.2 | 7.7 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
08 November 2024

| Time | Total | Vpp 85 | Mean | SD |
|--------------|------------|-------------|-------------|------------|
| 1300 | 4 - | | 28 | 5.5 |
| 1315 | 5 - | | 18.3 | 3.3 |
| 1330 | 3 - | | 21.4 | 4.1 |
| 1345 | 2 - | | 19.8 | 9.8 |
| 1400 | 6 - | | 23.3 | 2.6 |
| 1415 | 7 - | | 19.1 | 4.8 |
| 1430 | 4 - | | 21.4 | 4.5 |
| 1445 | 0 - | - | - | - |
| 1500 | 5 - | | 16.5 | 6.6 |
| 1515 | 8 - | | 20.3 | 2.9 |
| 1530 | 4 - | | 24.1 | 2.7 |
| 1545 | 7 - | | 21.8 | 4.4 |
| 1600 | 6 - | | 23.5 | 3.2 |
| 1615 | 34 | 20.6 | 17.4 | 3.6 |
| 1630 | 26 | 20.7 | 18.2 | 3 |
| 1645 | 10 - | | 21.5 | 4.2 |
| 1700 | 11 | 28.8 | 18.9 | 7.8 |
| 1715 | 11 | 25.6 | 19.6 | 6.9 |
| 1730 | 5 - | | 25 | 4.5 |
| 1745 | 2 - | | 26.6 | 1.1 |
| 1800 | 2 - | | 20.9 | 3.2 |
| 1815 | 6 - | | 17.9 | 3.6 |
| 1830 | 7 - | | 22.2 | 6.6 |
| 1845 | 3 - | | 18.9 | 5.6 |
| 1900 | 3 - | | 25.9 | 1.1 |
| 1915 | 6 - | | 22.8 | 5.8 |
| 1930 | 2 - | | 21 | 6.6 |
| 1945 | 0 - | - | - | - |
| 2000 | 0 - | - | - | - |
| 2015 | 1 - | | 27.5 - | - |
| 2030 | 2 - | | 23.4 | 5.1 |
| 2045 | 0 - | - | - | - |
| 2100 | 0 - | - | - | - |
| 2115 | 1 - | | 30.2 - | - |
| 2130 | 1 - | | 16 - | - |
| 2145 | 0 - | - | - | - |
| 2200 | 0 - | - | - | - |
| 2215 | 0 - | - | - | - |
| 2230 | 0 - | - | - | - |
| 2245 | 0 - | - | - | - |
| 2300 | 1 - | | 24.7 - | - |
| 2315 | 0 - | - | - | - |
| 2330 | 2 - | | 16.7 | 0.6 |
| 2345 | 0 - | - | - | - |
| 2400 | 1 - | | 22.7 - | - |
| 08-09 | 75 | 27.1 | 21.5 | 5.4 |
| 17-18 | 20 | 27.2 | 21.7 | 6.2 |
| 07-19 | 332 | 25.6 | 20.2 | 5.2 |
| 07-23 | 346 | 25.7 | 20.4 | 5.2 |
| 00-24 | 353 | 25.7 | 20.4 | 5.2 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
Grand Total

| Time | Total | Cls 1 | Cls 2 | Cls 3 | Cls 4 | Cls 5 | Cls 6 | Cls 7 | Cls 8 | Cls 9 | Cls 10 | Cls 11 |
|------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|--------|--------|
| -- | 2283 | 58 | 1879 | 0 | 103 | 228 | 15 | 0 | 0 | 0 | 0 | 0 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
Grand Total

| Time | Total | Cls 12 | CI% 1 | CI% 2 | CI% 3 | CI% 4 | CI% 5 | CI% 6 | CI% 7 | CI% 8 | CI% 9 | CI% 10 |
|------|-------|-----------|----------|----------|----------|----------|----------|----------|----------|----------|----------|-----------|
| -- | 2283 | 0 | 2.541 | 82.3 | 0 | 4.512 | 9.987 | 0.657 | 0 | 0 | 0 | 0 |

Site Name - 24379-09
 Description - Cleveland Walk, East of Bathwick Hill
 Direction - West
 Grand Total

| Time | Total | CI% 11 | CI% 12 | Vbin 0 5 | Vbin 5 10 | Vbin 10 15 | Vbin 15 20 | Vbin 20 25 | Vbin 25 30 | Vbin 30 35 | Vbin 35 40 | Vbin 40 45 |
|------|-------|-----------|-----------|----------------|-----------------|------------------|------------------|------------------|------------------|------------------|------------------|------------------|
| -- | 2283 | 0 | 0 | 9 | 39 | 195 | 781 | 880 | 328 | 43 | 7 | 0 |

Site Name - 24379-09
Description - Cleveland Walk, East of Bathwick Hill
Direction - West
Grand Total

| Time | Total | Vpp 85 | Mean | SD |
|------|-------|-----------|------|-----|
| -- | 2283 | 25.3 | 20.6 | 4.9 |