



# Site Photographs

---



Photo 1 – View west over yard area



Photo 2 – View west over yard area, bus depot and adjacent residential property



Photo 3 – View west over adjacent farm land



Photo 4 – View southeast from top of spoil heap



Photo 5 – View southeast to top of spoil heap (graded and levelled ground)



Photo 6 – Steep slope in southeast of the Site

# Site Photographs

---



Photo 7 – Steep slope in the west of the Site



Photo 8 – Bus Depot adjacent to the south of the yard area



Photo 9 – Building 1



Photo 10 – Capped mine shaft with Building 3 behind



Photo 11 – Building 5



Photo 12 – Building 6